other recent bridge. Alle		United States Environmenta	al Protection Agency		Form Ap	
\$EPA		Washington, D.	C. 20460		Approva	o. 2040-0057 al expires 10-31-95
ALIV	Wate	r Compliance Ir	rspection Repo	rt	Applote	
		Section A: National D	ata System Coding (i.e.	e., PCS)		
Transaction Code		PES	yy/mm/dd 2 0 1 1 0 1 0 ₁₇	Inspection Typ		spector Fac Type R 20 1
n s a m p I i n g	o n S	e p t 2 6 to 2 7	Remarks			
Inspection Work Days	Facility Self-	Monitoring Evaluation Ratin	g B1 QA	A737	1	Reserved
		Section	B: Facility Data			
Name and Location of Facility	Inspected (Fo	or industrial users discharging	ng to POTW, also	Entry Time	e/Date	Permit Effective Date
include POTW name and NDI				900 AM		October 26, 1994
City of Brockton WWTP				Oct 10, 20		
303 Oak Hill Way				Exit Time	Date	Permit Expiration Date
Brockton, MA 02401				400 PM		October 26, 1998
				Oct 10, 20		
Name(s) of On-Site Represer		s)/Phone and Fax Number(s	3)	Other Fac	ility Data	
Pat Flynn / Head Operator / 50						
John Kazlauskas / Project Ma	Hagel / 300 300	0-7003				
John Kazlauskas (US Filter op Bob Smith / DPW Commissio	perated) Same oner contacted	as above contacted yes d NO		No those areas ev	aluated)	
Bob Smith / DPW Commissio	perated) Same oner contacted Section C: Ar	as above contacted yes d NO reas Evaluated During I	X Yes X I	those areas ev		SO (sewer Overflow)
John Kazlauskas (US Filter op Bob Smith / DPW Commissio S	perated) Same oner contacted Section C: Ar	as above contacted yes d NO eas Evaluated During I	X Yes X Inspection (Check only X Operations & Ma	those areas ev	CSO/S	SO (sewer Overflow)
John Kazlauskas (US Filter op Bob Smith / DPW Commissio S X Permit Records/Reports	perated) Same oner contacted Section C: Ar	as above contacted yes d NO eas Evaluated During I Flow Measurement Self-Monitoring Program	X Yes X Inspection (Check only X Operations & Ma X Sludge Handling	those areas evi	CSO/S Pollution	on Prevention
John Kazlauskas (US Filter op Bob Smith / DPW Commission S X Permit Records/Reports X Facility Site Review	perated) Same oner contacted Section C: Ar	eas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules	X Yes X Inspection (Check only X Operations & Ma X Sludge Handling, Pretreatment	those areas evi	CSO/S Pollutio	on Prevention
John Kazlauskas (US Filter op Bob Smith / DPW Commission S X Permit Records/Reports X Facility Site Review X Effluent/Receiving War	perated) Same oner contacted Section C: Ar X X x tters	eas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory	X Yes X Inspection (Check only X Operations & Ma X Sludge Handling Pretreatment X Storm Water	those areas evi	CSO/S Pollutio X Multime Other:	on Prevention edia
John Kazlauskas (US Filter op Bob Smith / DPW Commission S X Permit Records/Reports X Facility Site Review X Effluent/Receiving War Section D: Sun	perated) Same oner contacted Section C: Ar X X X x x x x x x x x x x x x x x x x	eas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attac	X Yes X Inspection (Check only X Operations & Ma X Sludge Handling Pretreatment X Storm Water	those areas evi	CSO/S Pollutio X Multime Other:	on Prevention edia
John Kazlauskas (US Filter op Bob Smith / DPW Commission Smith / DPW	perated) Same oner contacted Section C: Ar X X X x x x x x x x x x x x x x x x x	eas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attacwith City of Brockton	X Yes X Inspection (Check only X Operations & Ma X Sludge Handling, Pretreatment X Storm Water ch additional sheets of inspection (Check only) Inspection (Check only) A provided the characteristics of inspection (Check only) Inspection (Check	those areas evi	CSO/S Pollutio X Multime Other:	on Prevention edia
John Kazlauskas (US Filter op Bob Smith / DPW Commission S X Permit Records/Reports X Facility Site Review X Effluent/Receiving War Section D: Sun Facility operated by US Filter Plant design flow 18 MGD with	perated) Same oner contacted Section C: Ar X X X X X X X X X X X X X X X X X X	as above contacted yes d NO reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attacwith City of Brockton GD, currently 17 - 18 MGD	X Yes X Inspection (Check only X Operations & Ma X Sludge Handling, Pretreatment X Storm Water Ch additional sheets of its	those areas evi	CSO/S Pollution X Multime Other:	on Prevention edia as necessary)
John Kazlauskas (US Filter op Bob Smith / DPW Commission Smith / DPW	perated) Same oner contacted Section C: Ar X X X X X X X X X X X X X X X X X X	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attacwith City of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and	X Yes X Inspection (Check only X Operations & Ma X Sludge Handling Pretreatment X Storm Water Storm Water Additional sheets of I 1/4 thick in clumps, step	those areas evi	CSO/S Pollution Multime Other:	as necessary)
John Kazlauskas (US Filter op Bob Smith / DPW Commission Signature of	Section C: Ar X X Atters mmary of Fine under contract th peak of 36 M charge extending e spill (est. 200-	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attac with City of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and	X Yes X I	those areas evaluation are also areas evaluation are areas evaluation areas evaluation are areas evaluation are areas evaluation areas evaluation are areas evaluation areas evaluation are areas evaluation areas evaluation are areas evaluation areas evaluation are areas evaluation areas evaluati	CSO/S Pollution Multime Other: ecklists a	as necessary) creates foam r to storm drain. NOT rep
John Kazlauskas (US Filter op Bob Smith / DPW Commission Signature of	perated) Same oner contacted Section C: Ar X X X X X X X X X X X X X X X X X X	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attac with City of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and 300 gal) to ground and the	X Yes X Inspection (Check only X Operations & Ma X Sludge Handling Pretreatment X Storm Water The additional sheets of Instantial Storm of Insta	those areas evi	CSO/S Pollution Multime Other: ecklists a on effluent g with water etected pH	on Prevention edia as necessary) creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill
John Kazlauskas (US Filter op Bob Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith Records/Reports X	perated) Same oner contacted Section C: Ar X X X X X X X X X X X X X X X X X X	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attac with City of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and 300 gal) to ground and ther coam and grass seed but mi 0 gal) to dike area from ove	X Yes X Inspection (Check only X Operations & Ma X Sludge Handling Pretreatment X Storm Water The additional sheets of Instantial Storm of Insta	those areas evi	CSO/S Pollution Other: ecklists a on effluent g with water etected pH water and	on Prevention edia as necessary) creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved
John Kazlauskas (US Filter op Bob Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith Records/Reports X	perated) Same oner contacted Section C: Ar X X X X X X X X X X X X X X X X X X	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attac with City of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and 300 gal) to ground and ther coam and grass seed but mi 0 gal) to dike area from ove	Inspection (Check only Inspection (Inspection (Inspec	those areas evi	CSO/S Pollution Other: ecklists a on effluent y with water and ement to steep	on Prevention edia as necessary) creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved orm drains. Reported to
Sob Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith Records/Reports Facility Site Review Effluent/Receiving War Section D: Sun Facility operated by US Filter Plant design flow 18 MGD with Some foam on river from discounce 15,2001 ferrous chlorided Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided pround and ran down 2 storm 5 gal plastic pail 1/2 full of 2,5	perated) Same oner contacted Section C: Ar X X X X X X X X X X X X X X X X X X	eas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attac with City of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and 300 gal) to ground and ther oam and grass seed but mi 0 gal) to dike area from ove paved area washed down eaking on floor of "telephone	Inspection (Check only X Operations & Ma X Sludge Handling. Pretreatment X Storm Water The additional sheets of the storm drain to river, cleen in the storm drain to river, cleen in the storm drain, very visible or e" / "electric" room of building.	those areas evinintenance //Disposal narrative and che cascade aeration of aned up by diluting st of soil & water do area contained rain rang stains on pavering # 12. Floor sta	CSO/S Pollution Other: ecklists a on effluent with water etected pH water and ement to ste in area ~ 3	on Prevention edia as necessary) creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved orm drains. Reported to l'
John Kazlauskas (US Filter op Bob Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith Records/Reports X	perated) Same oner contacted oner contacted oner contacted oner contacted oner contacted oner contract oner contract the peak of 36 M charge extending espill (est. 200-67) of spill, new I ride spill (est. 1 n drains to river, 5 -D herbicide le berm area, slue	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attactivity of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and coam and grass seed but mid ogal) to dike area from over paved area washed down eaking on floor of "telephone dige was <1/4 inch thick in a	Inspection (Check only X	those areas evinintenance //Disposal narrative and che cascade aeration of aned up by diluting st of soil & water do area contained rain rang stains on pavering # 12. Floor sta	CSO/S Pollution Other: ecklists a on effluent with water etected pH water and ement to ste in area ~ 3	on Prevention edia as necessary) creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved orm drains. Reported to 8 ' by 5'
John Kazlauskas (US Filter op Bob Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith Records/Reports Facility Site Review Effluent/Receiving War Section D: Sun Facility operated by US Filter Plant design flow 18 MGD with Some foam on river from discounce 15,2001 ferrous chlorided Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided pround and ran down 2 storm 5 gal plastic pail 1/2 full of 2,5 sludge leaking outside under Main pump station wet well an Flow reported by using hourly	perated) Same oner contacted oner contacted oner contacted oner contacted oner contacted oner contacted oner contract oner contact oner con	eas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attac with City of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and 300 gal) to ground and ther oam and grass seed but mi 0 gal) to dike area from ove paved area washed down eaking on floor of "telephone dige was <1/4 inch thick in a rged and walkway covered measurments that are ave	Inspection (Check only X	those areas evinintenance //Disposal narrative and che cascade aeration of aned up by diluting st of soil & water do area contained raing stains on pavering # 12. Floor state a would drain to state a would drain to state a state on influent mages area.	CSO/S Pollution Other: ecklists a on effluent g with water etected pH a water and ement to str in area ~ 3 torm water g meters ar	on Prevention edia as necessary) creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved orm drains. Reported to l by 5' drain to river nd 1 of the 2 parshall flum
John Kazlauskas (US Filter op Bob Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith Records/Reports Facility Site Review Effluent/Receiving War Section D: Sun Facility operated by US Filter Plant design flow 18 MGD with Some foam on river from discounce 15,2001 ferrous chlorided Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided pround and ran down 2 storm 5 gal plastic pail 1/2 full of 2,5 sludge leaking outside under Main pump station wet well an Flow reported by using hourly	perated) Same oner contacted oner contacted oner contacted oner contacted oner contacted oner contacted oner contract oner contact oner con	eas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attac with City of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and 300 gal) to ground and ther oam and grass seed but mi 0 gal) to dike area from ove paved area washed down eaking on floor of "telephone dige was <1/4 inch thick in a rged and walkway covered measurments that are ave	Inspection (Check only X	those areas evinintenance //Disposal narrative and che cascade aeration of aned up by diluting st of soil & water do area contained raing stains on pavering # 12. Floor state a would drain to state a would drain to state a state on influent mages area.	CSO/S Pollution Other: ecklists a on effluent g with water etected pH a water and ement to str in area ~ 3 torm water g meters ar	on Prevention edia as necessary) creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved orm drains. Reported to l by 5' drain to river nd 1 of the 2 parshall flum
John Kazlauskas (US Filter op Bob Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith / DPW Commission Smith Records/Reports X Facility Site Review X Effluent/Receiving War Section D: Sun Facility operated by US Filter Plant design flow 18 MGD with Some foam on river from discounce 15,2001 ferrous chlorided Dead grass in area (11' by 65 August 31, 2001 ferrous chlorider ground and ran down 2 storm 5 gal plastic pail 1/2 full of 2,5 sludge leaking outside under Main pump station wet well at Flow reported by using hourly Some dewatered sludge on devery 1-2 weeks and dispose	perated) Same oner contacted oner contacted oner contacted oner contacted oner contacted oner contacted oner contract on contact oner contact oner contact oner contract oner contact oner co	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attactive of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and 300 gal) to ground and there of the oam and grass seed but mid ogal) to dike area from over paved area washed down eaking on floor of "telephone didge was <1/4 inch thick in a gred and walkway covered to measurments that are average in the truck was almost full of the control of the	Inspection (Check only X	those areas evintenance //Disposal narrative and che cascade aeration of the	CSO/S Pollution Other: ecklists a on effluent g with water etected pH water and ement to sto in area ~ 3 torm water g meters are andfill, about	on Prevention edia as necessary) creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved orm drains. Reported to b by 5' drain to river and 1 of the 2 parshall flum at 1 truck load is generate
John Kazlauskas (US Filter op Bob Smith / DPW Commission Signature of Smith / DPW Commission Signature of Smith / DPW Commission Signature of Smith Records/Reports X	perated) Same oner contacted oner contacted oner contacted oner contacted oner contacted oner oner oner oner oner oner oner oner	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory C	Inspection (Check only X	those areas evintenance /Disposal narrative and che cascade aeration of the c	CSO/S Pollution Other: Decklists a connection effluent in water and in area ~ 3 items are and in area	creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved orm drains. Reported to b by 5' drain to river and 1 of the 2 parshall flum ut 1 truck load is generate
John Kazlauskas (US Filter of Bob Smith / DPW Commission Signature of Smith / DPW Commission Signature of Smith / DPW Commission Signature of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided pead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorided of Smith / Dead grass in area (11' by 65 Au	perated) Same oner contacted oner contacted oner contacted oner contacted oner contacted oner oner oner oner oner oner oner oner	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory C	Inspection (Check only X	those areas evintenance /Disposal narrative and che cascade aeration of the c	CSO/S Pollution Other: Decklists a connection effluent in water and in area ~ 3 items are and in area	creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved orm drains. Reported to b by 5' drain to river and 1 of the 2 parshall flum ut 1 truck load is generate
John Kazlauskas (US Filter op Bob Smith / DPW Commission Signature of Smith / DPW Commission Smith / D	perated) Same oner contacted oner contacted oner contacted oner contacted oner contacted oner oner oner oner oner oner oner oner	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory C	Inspection (Check only X	those areas evinintenance //Disposal narrative and che cascade aeration of the cascade aeration of the cascade aeration of the carea contained raing stains on pavering # 12. Floor state awould drain to state awould drain to state on influent magisposed in onsite latter inspection stains bungs and hadroken in open positions.	CSO/S Pollution Other: Decklists a connection effluent by with water and between the statement to statement to statement and a connection effluent by water and between the statement to statement to statement to statement to statement to statement to statement and statement and statement and statement by the statement of the s	creates foam r to storm drain. NOT rep < 1 to pH 3 in soil at spill both pumped to paved orm drains. Reported to b by 5' drain to river and 1 of the 2 parshall flum ut 1 truck load is generate
John Kazlauskas (US Filter of Bob Smith / DPW Commission Smith / Dead grass in area (11' by 65 August 31, 2001 ferrous chlorid ground and ran down 2 storm 5 gal plastic pail 1/2 full of 2,5 sludge leaking outside under Main pump station wet well at Flow reported by using hourly Some dewatered sludge on devery 1-2 weeks and dispose	perated) Same oner contacted oner contacted oner contacted oner contacted oner contacted oner contacted oner contract on contact oner contact oner contact oner contract oner contact oner co	reas Evaluated During I Flow Measurement Self-Monitoring Program Compliance Schedules Laboratory dings/Comments (Attactive of Brockton GD, currently 17 - 18 MGD g ~50 feet downstream and 300 gal) to ground and there of the oam and grass seed but mid ogal) to dike area from over paved area washed down eaking on floor of "telephone didge was <1/4 inch thick in a gred and walkway covered to measurments that are average in the truck was almost full of the control of the	Inspection (Check only X	those areas evintenance //Disposal narrative and che cascade aeration of the	CSO/S Pollution Other: ecklists a on effluent g with water etected pH water and ement to sto in area ~ 3 torm water g meters are andfill, about	on Prevention edia as necessary) creates foam r to storm drain. NO < 1 to pH 3 in soil at both pumped to pay orm drains. Reporte by 5' drain to river and 1 of the 2 parshall ut 1 truck load is gen

Agency/Office/Phone and Fax Numbers



Signature of Management QA Reviewer

CAT30124 968

Date

€.EPA

United States Environmental Protection Agency

Washington, D.C. 20460

Form Approved. OMB No. 2040-0057 Approval expires 10-31-95

	ater Compliance Ins	Contam Coding (i.e. D	CS)	
	Section A: National Data	a System Coding (i.e., P	Inspection Type	Inspector Fac Type
Transaction Code 1 N 2 5 3 M A 0	NDPES 1 0 1 0 1 0 1 1 1 12	yy/mm/dd 0 1 1 0 1 0 17	18 S	~19 R 20 1
		emarks 2 0 0 1		
sampling on	S e p t 2 6 to 2 7	2001		
	Self-Monitoring Evaluation Rating	B1 QA 71 N 72	73 74	75 80
. 69		: Facility Data		
Name and Location of Facility Inspected			Entry Time/Dat	e Permit Effective Date
include POTW name and NDPES perm	it number)		900 AM	October 26, 1994
City of Brockton WWTP	(mamber)		Oct 10, 2001	
303 Oak Hill Way			Exit Time/Date	
Brockton, MA 02401			400 PM	October 26, 1998
			Oct 10, 2001	
Name(s) of On-Site Representative(s)/	Fitle(s)/Phone and Fax Number(s)		Other Facility [Data
Pat Flynn / Head Operator / 508 580-78	85			
John Kazlauskas / Project Manager / 50	8 580-7885			
" OCC :-15	Title /Dhane and Fay Number			
Name, Address of responsible Official/ John K zlauskas (US Filter operated) S	ame as above contacted ves			
John Kazlauskas (US Filter operated) S Bob Smith / DPW Commissioner con	tacted NO	Contacted		
Bob Sr ith 7 DPVV Commissioner Com	lacted 110	X Yes X No		
9 1: 6	: Areas Evaluated During Ins	enection (Check only tho	se areas evalua	ted)
Section C				SO/SSO (sewer Overflow)
X Permit	X Flow Measurement	X Operations & Mainter		collution Prevention
.Records/Reports	X Self-Monitoring Program	X Sludge Handling/Disp Pretreatment		Multimedia
X Facility Site Review	Compliance Schedules	X Storm Water		Other:
X Effluent/Receiving Waters	Laboratory	Otolini Trans	ii alaaaki	into an nagos and
		additional chaote of narr		
Section D: Summary of	Findings/Comments (Attach	additional sheets of han	ative and checki	ists as necessary
Section D: Summary of Facility operated by US Filter under cor	tract with City of Brockton	additional sneets of hair	ative and checki	ists as necessary)
Section D: Summary of Facility operated by US Filter under cor	atract with City of Brockton			
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of	ntract with City of Brockton 36 MGD, currently 17 - 18 MGD	1/4 thick in clumps, step case	cade aeration on eff	luent creates foam
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and <	1/4 thick in clumps, step case	cade aeration on eff	luent creates foam water to storm drain. NOT repo
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to	1/4 thick in clumps, step case o storm drain to river, cleaned mal growth. pH paper test of	cade aeration on eff d up by diluting with soil & water detecte	luent creates foam water to storm drain. NOT repo ed pH < 1 to pH 3 in soil at spill :
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill,	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining	1/4 thick in clumps, step case o storm drain to river, cleaned mal growth, pH paper test of	cade aeration on eff d up by diluting with soil & water detecte contained rain wate	luent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill to payed to payed
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill,	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining est. 10 gal) to dike area from over former, payed area washed down st	1/4 thick in clumps, step case ostorm drain to river, cleaned all growth, pH paper test of illing storage tank, dike area form drain, very visible orang	cade aeration on eff d up by diluting with soil & water detecte contained rain wate stains on pavemen	luent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to E
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining est. 10 gal) to dike area from over foreign paved area washed down st ended leaking on floor of "telephone"	1/4 thick in clumps, step case of storm drain to river, cleaned all growth, pH paper test of illing storage tank, dike area orm drain, very visible orang for the control of building for the control of the control of the case or the control of the case of the	cade aeration on eff d up by diluting with soil & water detecte contained rain wate stains on pavemen 12. Floor stain are	luent creates foam water to storm drain. NOT repeted pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to Ea ~ 3' by 5'
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbic sludge leaking outside under berm area	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining est. 10 gal) to dike area from over fi river, paved area washed down st cide leaking on floor of "telephone" a, sludge was <1/4 inch thick in are	1/4 thick in clumps, step case of storm drain to river, cleaned mal growth, pH paper test of illing storage tank, dike area orm drain, very visible orang / "electric" room of building # a 3' by 5', during rain area w	cade aeration on eff d up by diluting with soil & water detecte contained rain wate stains on pavemen 12. Floor stain are	luent creates foam water to storm drain. NOT repeted pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to Ea ~ 3' by 5'
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has su	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining est. 10 gal) to dike area from over fiver, paved area washed down st cide leaking on floor of "telephone" a, sludge was <1/4 inch thick in are urcharged and walkway covered with	1/4 thick in clumps, step case of storm drain to river, cleaned all growth, pH paper test of illing storage tank, dike area orm drain, very visible orang and "electric" room of building and any of the company of the	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm	nuent creates foam water to storm drain. NOT repeted pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to Ea ~ 3' by 5' water drain to river ers and 1 of the 2 parshall flume
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under bern area Main pump station wet well area has su	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining est. 10 gal) to dike area from over fiver, paved area washed down st cide leaking on floor of "telephone" a, sludge was <1/4 inch thick in are urcharged and walkway covered with	1/4 thick in clumps, step case of storm drain to river, cleaned all growth, pH paper test of illing storage tank, dike area orm drain, very visible orang and "electric" room of building and any of the company of the	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm	nuent creates foam water to storm drain. NOT repeted pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to Ea ~ 3' by 5' water drain to river ers and 1 of the 2 parshall flume
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbic sludge leaking outside under berm area Main pump station wet well area has st Flow reported by using hourly instantar Some dewatered sludge on conveyor because of the least of the	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining est. 10 gal) to dike area from over foriver, paved area washed down st cide leaking on floor of "telephone". a, sludge was <1/4 inch thick in are urcharged and walkway covered with the truck was almost full of or	1/4 thick in clumps, step case to storm drain to river, cleaner all growth, pH paper test of illing storage tank, dike area orm drain, very visible orang / "electric" room of building as as by 5', during rain area with 6 inches of solids ged, There are no totalizers as collected in truck and dispose the storage of the s	cade aeration on eff d up by diluting with soil & water detects contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill	luent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to Eaa ~ 3' by 5' water drain to river lers and 1 of the 2 parshall flument, about 1 truck load is generated.
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar.	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining est. 10 gal) to dike area from over foriver, paved area washed down st cide leaking on floor of "telephone". a, sludge was <1/4 inch thick in are urcharged and walkway covered with the truck was almost full of or	1/4 thick in clumps, step case to storm drain to river, cleaner all growth, pH paper test of illing storage tank, dike area orm drain, very visible orang / "electric" room of building as as by 5', during rain area with 6 inches of solids ged, There are no totalizers as collected in truck and dispose the storage of the s	cade aeration on eff d up by diluting with soil & water detects contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill	luent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to Eaa ~ 3' by 5' water drain to river lers and 1 of the 2 parshall flument, about 1 truck load is generated.
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stored outside the store of the store dewatered sludge on conveyor be every 1-2 weeks and disposed in the later the store outside store outside.	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining est. 10 gal) to dike area from over friver, paved area washed down st cide leaking on floor of "telephone", a, sludge was <1/4 inch thick in are urcharged and walkway covered with neous measurments that are average by passes route to incinerator and is andfill, the truck was almost full of or the course of the co	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang of "electric" room of building as as by 5', during rain area with 6 inches of solids ged, There are no totalizers of collected in truck and disposed ewatered sludge during the eand 7 of them were missing	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavemen 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old	luent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to Eaa ~ 3' by 5' water drain to river lers and 1 of the 2 parshall flument, about 1 truck load is generated.
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar Some dewatered sludge on conveyor bevery 1-2 weeks and disposed in the latempty polymer totes are stored outside containment dike for 8000 gal sodium line.	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < 200-300 gal) to ground and then to mew loam and grass seed but mining est. 10 gal) to dike area from over fiver, paved area washed down st cide leaking on floor of "telephone" a, sludge was <1/4 inch thick in are urcharged and walkway covered with theous measurments that are average by passes route to incinerator and is andfill, the truck was almost full of the theous measurments that are average to provide the control of the control	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang of "electric" room of building as as by 5', during rain area with 6 inches of solids ged, There are no totalizers of collected in truck and disposed ewatered sludge during the eand 7 of them were missing	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavemen 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old en in open position	luent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to Eaa ~ 3' by 5' water drain to river lers and 1 of the 2 parshall flument, about 1 truck load is generated.
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar Some dewatered sludge on conveyor bevery 1-2 weeks and disposed in the latempty polymer totes are stored outside containment dike for 8000 gal sodium Name(s) and Signature(s) of Inspector	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < 200-300 gal) to ground and then to mew loam and grass seed but mining est. 10 gal) to dike area from over for iver, paved area washed down stoide leaking on floor of "telephone" a, sludge was <1/4 inch thick in area urcharged and walkway covered with the ous measurments that are average to passes route to incinerator and is andfill, the truck was almost full of the court of the course of the cou	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang and "electric" room of building and a by 5', during rain area with 6 inches of solids ged, There are no totalizers a collected in truck and disposed watered sludge during the e and 7 of them were missing in to sewer, drain valve brokes.	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old en in open position	iluent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to E are ~ 3' by 5' water drain to river ters and 1 of the 2 parshall flumed, about 1 truck load is generated.
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar Some dewatered sludge on conveyor be every 1-2 weeks and disposed in the latempty polymer totes are stored outside containment dike for 8000 gal sodium leads of the store of the s	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < 200-300 gal) to ground and then to mew loam and grass seed but mining est. 10 gal) to dike area from over for iver, paved area washed down stoide leaking on floor of "telephone" a, sludge was <1/4 inch thick in area urcharged and walkway covered with the ous measurments that are average to passes route to incinerator and is andfill, the truck was almost full of the court of the course of the cou	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang a 3' by 5', during rain area with 6 inches of solids ged, There are no totalizers a collected in truck and disposed watered sludge during the e and 7 of them were missing in to sewer, drain valve broke gency/Office/Phone and Fax	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old en in open position	iluent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to E are ~ 3' by 5' water drain to river ters and 1 of the 2 parshall flumed, about 1 truck load is generated. It polymer/rain water in them
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar Some dewatered sludge on conveyor bevery 1-2 weeks and disposed in the latempty polymer totes are stored outside containment dike for 8000 gal sodium Name(s) and Signature(s) of Inspecto	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < 200-300 gal) to ground and then to mew loam and grass seed but mining est. 10 gal) to dike area from over for iver, paved area washed down stoide leaking on floor of "telephone" a, sludge was <1/4 inch thick in area urcharged and walkway covered with the ous measurments that are average to passes route to incinerator and is andfill, the truck was almost full of the court of the course of the cou	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang a 3' by 5', during rain area with 6 inches of solids ged, There are no totalizers a collected in truck and disposed watered sludge during the e and 7 of them were missing in to sewer, drain valve broke gency/Office/Phone and Fax	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old en in open position	iluent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to E are ~ 3' by 5' water drain to river ters and 1 of the 2 parshall flumed, about 1 truck load is generated. It polymer/rain water in them
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar Some dewatered sludge on conveyor bevery 1-2 weeks and disposed in the latempty polymer totes are stored outside containment dike for 8000 gal sodium Name(s) and Signature(s) of Inspecto	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < 200-300 gal) to ground and then to mew loam and grass seed but mining est. 10 gal) to dike area from over for iver, paved area washed down stoide leaking on floor of "telephone" a, sludge was <1/4 inch thick in area urcharged and walkway covered with the ous measurments that are average to passes route to incinerator and is andfill, the truck was almost full of the court of the course of the cou	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang a 3' by 5', during rain area with 6 inches of solids ged, There are no totalizers a collected in truck and disposed watered sludge during the e and 7 of them were missing in to sewer, drain valve broke gency/Office/Phone and Fax	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old en in open position	iluent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to E are ~ 3' by 5' water drain to river ters and 1 of the 2 parshall flumed, about 1 truck load is generated. It polymer/rain water in them
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar Some dewatered sludge on conveyor bevery 1-2 weeks and disposed in the latempty polymer totes are stored outside containment dike for 8000 gal sodium Name(s) and Signature(s) of Inspector	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < 200-300 gal) to ground and then to mew loam and grass seed but mining est. 10 gal) to dike area from over for iver, paved area washed down stoide leaking on floor of "telephone" a, sludge was <1/4 inch thick in area urcharged and walkway covered with the ous measurments that are average to passes route to incinerator and is andfill, the truck was almost full of the court of the course of the cou	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang a 3' by 5', during rain area with 6 inches of solids ged, There are no totalizers a collected in truck and disposed watered sludge during the e and 7 of them were missing in to sewer, drain valve broke gency/Office/Phone and Fax	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old en in open position	iluent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to E are ~ 3' by 5' water drain to river ters and 1 of the 2 parshall flumed, about 1 truck load is generated. It polymer/rain water in them
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar Some dewatered sludge on conveyor bevery 1-2 weeks and disposed in the latempty polymer totes are stored outside containment dike for 8000 gal sodium Name(s) and Signature(s) of Inspector	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < 200-300 gal) to ground and then to mew loam and grass seed but mining est. 10 gal) to dike area from over for iver, paved area washed down stoide leaking on floor of "telephone" a, sludge was <1/4 inch thick in area urcharged and walkway covered with the ous measurments that are average to passes route to incinerator and is andfill, the truck was almost full of the the outprochlorite (12-13%) tank has drained.	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang a 3' by 5', during rain area with 6 inches of solids ged, There are no totalizers a collected in truck and disposed watered sludge during the e and 7 of them were missing in to sewer, drain valve broke gency/Office/Phone and Fax	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old en in open position	iluent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to E are ~ 3' by 5' water drain to river ters and 1 of the 2 parshall flumed, about 1 truck load is generated. It polymer/rain water in them
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar Some dewatered sludge on conveyor bevery 1-2 weeks and disposed in the latempty polymer totes are stored outside containment dike for 8000 gal sodium Name(s) and Signature(s) of Inspector	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < 200-300 gal) to ground and then to mew loam and grass seed but mining est. 10 gal) to dike area from over for iver, paved area washed down stoide leaking on floor of "telephone" a, sludge was <1/4 inch thick in area urcharged and walkway covered with the ous measurments that are average to passes route to incinerator and is andfill, the truck was almost full of the the outprochlorite (12-13%) tank has drained.	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang a 3' by 5', during rain area with 6 inches of solids ged, There are no totalizers a collected in truck and disposed watered sludge during the e and 7 of them were missing in to sewer, drain valve broke gency/Office/Phone and Fax	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old en in open position	iluent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to E are ~ 3' by 5' water drain to river ters and 1 of the 2 parshall flumed, about 1 truck load is generated. It polymer/rain water in them
Section D: Summary of Facility operated by US Filter under cor Plant design flow 18 MGD with peak of Some foam on river from discharge ext June 15,2001 ferrous chloride spill (est Dead grass in area (11' by 65') of spill, August 31, 2001 ferrous chloride spill (ground and ran down 2 storm drains to 5 gal plastic pail 1/2 full of 2,5 -D herbid sludge leaking outside under berm area Main pump station wet well area has stellow reported by using hourly instantar Some dewatered sludge on conveyor bevery 1-2 weeks and disposed in the latempty polymer totes are stored outside containment dike for 8000 gal sodium Name(s) and Signature(s) of Inspector	atract with City of Brockton 36 MGD, currently 17 - 18 MGD ending ~50 feet downstream and < . 200-300 gal) to ground and then to new loam and grass seed but mining est. 10 gal) to dike area from over foriver, paved area washed down st cide leaking on floor of "telephone". a, sludge was <1/4 inch thick in are urcharged and walkway covered with the eous measurments that are average by passes route to incinerator and is the proposition of the following transport of the following transport and fill, the truck was almost full of the proposition of the following transport (12-13%) tank has draing transport A U.S. A U.S.	1/4 thick in clumps, step case of storm drain to river, cleaned and growth, pH paper test of illing storage tank, dike area orm drain, very visible orang a 3' by 5', during rain area with 6 inches of solids ged, There are no totalizers a collected in truck and disposed watered sludge during the e and 7 of them were missing in to sewer, drain valve broke gency/Office/Phone and Fax	cade aeration on eff d up by diluting with soil & water detecte contained rain water stains on pavement 12. Floor stain are rould drain to storm on influent mag met sed in onsite landfill inspection g bungs and had old en in open position Numbers -8358	iluent creates foam water to storm drain. NOT reported pH < 1 to pH 3 in soil at spill are and both pumped to paved to storm drains. Reported to E are ~ 3' by 5' water drain to river ters and 1 of the 2 parshall flumed, about 1 truck load is generated. It polymer/rain water in them



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION I 11 Technology Drive, Chelmsford, MA 01863

Inspection Report

Date: June 22, 2005

Subj: Brockton Wastewater Treatment Plant - MA0101010

303 Oak Hill Way

Brockton, MA 02301 - TEL 508-580-7885

NPDES Compliance Evaluation Inspection, May 25, 2005

Inspector:

Rich Fisher, Environmental Engineer USEPA/OEME/EIA

On May 25, 2005, I conducted a NPDES compliance evaluation inspection at the Brockton wastewater treatment facility in Brockton, MA. The facility contact during the inspection was Jim Lauzon, responsible official and Project Manager for Veolia Water, the contract operator. Currently, the plant's design capacity is 18.4 MGD and is operated by 30 employees with 24 hr/7 day coverage. Standard staffing consists of three people per shift. In addition to municipal sewerage from Brockton, the facility receives approximately 1 MGD each from Abington and Whitman.

The facility is being upgraded in three phases. Mr. Lauzon stated that Phase I construction is underway, Phase II is currently going out to bid, and a kickoff meeting to discuss the forthcoming Phase II was scheduled for the week of the inspection. He stated that Phase I consists primarily of electrical work and implementation of a new primary effluent pump station. During the ongoing upgrade phase, one aeration tank out of the seven is off-line while walls are constructed for the purpose of creating an anoxic zone and fine-bubble diffusers are installed. After approximately one month when this aeration basin upgrade is completed, another aeration basin will be taken off-line for a similar upgrade. Mr. Lauzon stated that the three aeration basins in the "south train" will all have to be taken off-line to install new blowers. He stated that since all the wastewater will be diverted to the "north train" during this portion of the upgrade, this work may be conducted during a low-flow period in the fall.

Mr. Lauzon stated that there are ongoing upgrades to the collection system to minimize the effects of inflow/infiltration (I/I). He couldn't provide information on these activities because Veolia Water is not tasked with managing the collection system with the exception of the two municipally-owned pump stations (a third is on private property). He stated that both pump stations were being tied into the POTW's SCADA system. Both stations have backup power in the form of diesel generator stets. High level alarms currently trigger a beacon at the plant, but will be tied into the plant SCADA

system within a couple weeks of the inspection. He stated that storm drains at the facility drain directly to the river.

Unit processes observed:

- 1. Grit tanks one of two is on-line; ferric chloride added for phosphorus removal; plant water running into the on-line grit chamber.
- 2. Primary clarification primary effluent flows through a channel immediately adjacent to the chlorine contact chamber.
- 3. Flow split into north and south trains.
- 4. South train aeration basins one of three off-line while diffusers and baffles being installed
- 5. Chlorine contact chamber river level observed to be almost as high as the level in the contact chamber.
- 6. Dissolved air floatation (DAF) units two of four on-line; will be replaced with two gravity belt thickeners during Phase II of the upgrade; sludge pumped to sludge storage tanks, mixed with primary sludge, centrifuged, and incinerated on the Brockton facility incinerates only sludge generated on site, except a small amount from the Veolia-operated Cohasset facility.

Facility laboratory:

Bill Brodeur, Senior Lab Technician, was the facility contact during this portion of the inspection. A Hach Pocket Colorimeter is used to analyze plant effluent for residual chlorine. Mr. Brodeur stated that three grab samples are collected each day, and that further samples are collected for analysis should the original three samples result in an average that is above the permit limit. The calibration of the colorimeter is checked once per day with potassium permanganate.

New automatic influent composite sampler was being installed before the grit chambers. In the meantime, the facility was collecting manual 1-liter aliquots every two hours for composite samples. These aliquots are manually flow-proportioned. Effluent composite samples are collected automatically by a time-paced unit collecting 500 ml/hr.

Dilution water in the laboratory is generated using reverse osmosis and filtration. No check of this water quality is conducted although the filters are changed every two years. One phosphorus standard solution was beyond expiration date and so Mr. Brodeur dumped it during the inspection. The pH meter is calibrated with 4, 7, and 10 S.U. buffer solutions. The 10 S.U. solution had expired in January, 2005. No documentation was available to demonstrate that the flow meters have been calibrated – including the influent flow meter which is used to activate chlorine injection according to Mr. Lauzon. The methods and apparatus for analyzing effluent for chlorine, TSS, fecal coliform, phosphorus, CBOD, and ammonia were all observed.

\$EPA

United States Environmental Protection Agency

Washington, D.C. 20460

Form Approved.

OMB No. 2040-0057

Approval expires 10-31-95

Water Compliance Ins	pection Report
----------------------	----------------

	Section A: National Dat	ta System Coding (i.e., P	CS)	19 2 300 19 72 372 4
	NDPES	yy/mm/dd 0 5 0 5 2 5 17	Inspection Type	Inspector Fac Type 19 R 20 1
1	R	Remarks		66
Inspection Work Days Facility Se	If-Monitoring Evaluation Rating	71 72	73 74	Reserved75 80
	Section E	3: Facility Data		
Name and Location of Facility Inspected (include POTW name and NDPES permit n Brockton Wastewater Treatment Facility 303 Oak Hill Way Brockton, MA 02301	number)	to POTW, also	Exit Time/Date	
Name(s) of On-Site Representative(s)/Title Jim Lauzon/Project Manager/508-580-78 Name, Address of responsible Official/Titl Jim Lauzon/Project Manager/508-580-78	e/Phone and Fax Number.		Other Facility D	oata
	Areas Evaluated During In	Contacted X Yes No nspection (Check only the		
X Permit X Records/Reports X Facility Site Review X Effluent/Receiving Waters	X Flow Measurement Self-Monitoring Program Compliance Schedules X Laboratory indings/Comments (Attach	X Operations & Mainte X Sludge Handling/Dis Pretreatment X Storm Water	posal P	CSO/SSO (sewer Overflow) Pollution Prevention Multimedia Other:
Report to follow.				
Name(s) and Signature(s) Inspector(s) Richard Fisher		Agency/Office/Phone and Fax USEPA/EIA (617) 918-8318	< Numbers	Date June 15, 2005
Signature of Management QA Reviewer		Agency/Office/Phone and Fax	x Numbers	Date



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Region 1 New England
Office of Environmental Measurement and Evaluation
11 Technology Drive, N. Chelmsford, MA 01863

Memorandum

Date: October 11, 2001

Subj: Brockton Wastewater Treatment Plant, possible RCRA issues

Brockton, MA

From: Daniel Granz, EIA

To: Ken Rota, SER,

On October 10, 2001, Daniel Granz visited the Brockton wastewater Treatment Plant located at 303 Oak Hill Way in Brockton, MA. to complete an NPDES inspection at the facility. The facility representative for the tour was Pat Flynn, Head Operator, and at the end of the inspection the debriefing was with John Kazlauskas, Project Manager. The municipal wastewater treatment facility is operated by US Filter employees under contract with the City of Brockton. The facility phone number is (508) 580-7885.

The facility uses ferrous chloride addition in the wastewater to precipitate phosphorus. There were two spills of ferrous chloride that went down storm drains to the Salisbury Plain River.

June 15, 2001 Spill

An approximately 4000-gallon tank was located on top of the wastewater channel grate between the grit chambers and primary clarifiers. The typical operation up to 6/15/01 was to fill the tank with ferrous chloride and allow it to drip by gravity into the wastewater stream. Ferrous chloride was pumped from an outside diked 7000 gallon storage tank to the feed tank located over the wastewater channel.

According to Mr. Flynn, 3000 gallons of ferrous chloride was in the 4000-gallon feed tank at 1200 A.M. on 6/15/01. The feed tank had a major leak which was discovered around 500 A.M. on 6/15/01. The ferrous chloride leak went into the wastewater channel and onto the ground. The spill on the ground ran down a grassed hill onto pavement and toward the stormwater drains. The ferrous spill was NOT captured but was hosed down into the storm drain to the river. The amount spilled

onto the ground was estimated at 200-300 gallons according to Mr. Flynn. He was not present when the spill occurred.

The 4000-gallon feed tank was drained into the wastewater stream and removed from the channel grating. The tank was still on site between the sand filter building and river. The tank was examined and appeared "clean" with no residual ferrous chloride in it. Since the June 15, 2001-spill, the ferrous chloride has been slowly pumped from the main storage tank to the entry point into the wastewater stream at the location where the feed tank had been located.

An area of approximately 11 feet by 65 feet sloping down the hill had no grass. It appeared to have new loam and grass seed in it. There were some adjacent areas that had new grass growing. I tested several areas for pH where there was no grass growing. I dug into the underlying soil about one inch, then placed distilled water in the depression, and then using pH indicator paper measured the pH. The following pH readings were obtained: ~ 2.5 -3, ~ 2 , ~ 2.5 , and < 1. The pH < 1 was located in the soil at the top of the hill next to where the feed tank was located. No soil at greater than 1 inch was tested.

Mr. Flynn and Mr. Kazlauskas were told the ferrous chloride spill still needed to be remediated. The facility has lime on site for use in the wastewater treatment plant. I told them since the ferrous chloride spilled was a pH <1 and there was residual in the soil of pH <1 that the waste may be considered a RCRA waste requiring approval from MADEP/EPA for treatment of the low pH soil with lime. I also told them that they could not simply dig up the contaminated soil and dump it in the on site landfill used for wastewater treatment solids.

Mr. Kazlauskas said the June 15, 2001, ferrous chloride spill was NOT reported to EPA or MADEP.

August 31, 2001 Spill

On August 31, 2001, the 7000-gallon ferrous chloride storage tank was filled. The tank was over filled and approximately 10 gallons spilled into the containment dike area. The dike area contained rain water also. The rain water and ferrous chloride were pumped out of the dike area onto the pavement and ran into two storm drains to the river.

During the inspection, there were very visible orange colored iron stains on the pavement leading to the storm drains. Distilled water was placed on four areas of the stained pavement and then tested with pH indicator paper. The pH was approximately 6. Directly under the fill pipe to the tank was a small puddle of yellow liquid on the pavement outside the containment dike. The pH of the liquid was pH <1 using pH paper.

Mr. Kazlauskas said the August 31, 2001, ferrous chloride spill was reported to EPA and MADEP.

Herbicide Spill

In the lower level of Building #12 in the "telephone" / "electric" room, there is a leaking 5 gallon white plastic pail labeled containing 2,4 -D. There was wet staining (approximately 5' by 3' area) on the concrete floor under and around the bucket of herbicide. The container was approximately half full. The spill extended to a small "dry" transformer and under some old window screens.

Hydrochloric Acid Storage

There is a 5000-gallon tank about half full of dilute hydrochloric acid in the basement level of the sludge building. The acid solution was tested with pH paper and found to be a pH of <1. The hydrochloric acid solution was used in the past to clean the sludge plate screens for the filter press. The two plate filter presses have not been used for more than 2 years. U S Filter has operated a centrifuge on site for dewatering sludge for the past 2+ years. The hydrochloric acid tank has no dike around it and is located adjacent to the floor trench drain leading to the wastewater treatment system.

cc: Steve Couto, SEW

Dan Granz

To: Don Grant/R1/USEPA/US@EPA

10/15/01 01:40 PM

Subject: SPCC 308 possibility

Don.

I was at Brockton, MA POTW last week (October 10) and I suspect they need an SPCC plan and none was seen while on site. I do not have the exact amounts of petroleum products stored at the facility which is operated by the contractor US Filter.

500 gal AST diesel fuel tank outside, for portable pumps

275 gal AST diesel fuel tank on portable generator trailer in garage

est. 500 - 1000 gal AST diesel fuel tank in base of 06 lift station generator

est. 50 gal AST day tank for main pump station generator, inside building

est. 5000-10000 AST ?fuel oil tank for incinerator, inside building in concrete vault room, door to room-

est. 5-10 55 gallon drums of varios oil lubricants in side buildings

est. 2000 gal UST diesel fuel for main pump station generator

3 large pad mounted transformers (may actually be two on eack pad) est. a total of several hundred gallons of fluid

There are water issues, potential RCRA, and potential CERCLA issues from two ferrous chloride spills at

Contractors Comps fambs > 6 mos

and Steve C., Ken R., and Don M. / Ray D. have been notified.

Contact at facility:

John Kazlauskas Project Manager - US Filter Brockton WWTP 303 Oak Hill Way Brockton, MA 02401 (508) 580-7895

Town contact:

Bob Smith DPW Commissioner

(I do not have phone number or address)

WANDA: PLEASE DRAFT A



U.S. ENVIRONMENTAL PROTECTION AGENCY SPCC FIELD INSPECTION AND PLAN REVIEW CHECKLIST

FOR USE AT ONSHORE FACILITIES (EXCLUDING PRODUCTION)

Overview of the Checklist

This checklist is designed to assist EPA inspectors in conducting a thorough and consistent inspection of a facility's compliance with the Spill Prevention, Control, and Countermeasure (SPCC) rule at 40 CFR part 112. It is a tool to help federal inspectors (or their contractors) record observations during the site visit and review of the SPCC Plan. While the checklist is comprehensive, the inspector should always refer to the SPCC rule in its entirety, the SPCC Regional Inspector Guidance Document, and other relevant guidance for evaluating compliance. This checklist must be completed in order for an inspection to count toward an agency measure (i.e., OEM/OECA inspection measures or GPRA).

The checklist is organized according to the SPCC rule. Each item in the checklist identifies the relevant section and paragraph in 40 CFR part 112 where that requirement is stated. Sections 112.1 through 112.5 specify the applicability of the rule and requirements for the preparation, implementation, and amendment of SPCC Plans. For these sections, the checklist includes data fields to be completed, as well as several questions with "yes" or "no" answers.

Sections 112.7 through 112.12 specify requirements for spill prevention, control, and countermeasures. For these sections, the inspector needs to evaluate whether the requirement is addressed adequately or inadequately in the SPCC Plan and whether it is implemented adequately in the field (either by field observation or record review). For the SPCC Plan and implementation in the field, if a requirement is addressed adequately, mark the "Yes" box in the appropriate column. If a requirement is not addressed adequately, mark the "No" box. If a requirement does not apply to the particular facility, mark the "NA" box. If a provision of the rule applies only to the SPCC Plan, the "Field" column is shaded.

Space is provided in each section to record comments. Additional space is available on the comments page at the end of the checklist. Comments should remain factual and support the evaluation of compliance.

Appendix A is for recording information about containers and other locations at the facility that require secondary containment.

Appendix B is a checklist for documentation of the tests and inspections the facility operator is required to keep with the SPCC Plan.

Appendix C is a checklist for oil removal contingency plans. A contingency plan is required if a facility determines that secondary containment is impracticable as provided in 40 CFR 112.7(d).



U.S. ENVIRONMENTAL PROTECTION AGENCY SPCC FIELD INSPECTION AND PLAN REVIEW CHECKLIST

FOR USE AT ONSHORE FACILITIES (EXCLUDING PRODUCTION)

FACILITY INFORMATION					
FACILITY NAME: Brockfor	Wastewa	ter Treat	ment F	2/a	ut
ADDRESS: 303 Oak	fill Wa	y	LAT:		LONG:
CITY: Brockton	STATE: MA	ZIP: 02401	COUNTY:	7	
TELEPHONE:	FACILITY REPRE	SENTATIVE NAME:	David	N	orton
OWNER NAME: City of P	Svocktor	, MA			
OWNER ADDRESS: City Hall	45 S	chool Stra	et		
CITY: Brockton	STATE: MA	ZIP: 02301			
TELEPHONE: 508 580 7135	OWNER CONTAC	CT PERSON: Mile	call TI	core	30h
FACILITY OPERATOR NAME (IF DIFFER	ENT FROM OWNE	R – IF NOT, PRINT "SA	ME"):		
OPERATOR ADDRESS: Veolia	- Water	North A.	merica		
CITY: Brockton	STATE: MA	ZIP: 02301		1	
TELEPHONE: 508 580 7885	OPERATOR CON	ITACT PERSON:	ines	La	uzou
FACILITY TYPE: POTW			NAICS CODE	<u>:</u>	
HOURS PER DAY FACILITY ATTENDED:	24	TOTAL FACILITY CAP	ACITY: 32	-, 75	56
TYPE(S) OF OIL STORED: Fuel	oil, lub	e oil, wa	ste oil	, d	iese
IS FACILITY LOCATED IN INDIAN COUN	TRY? 🗆 YES 🖼	O IF YES, RESERVA	TION NAME:	<i>'</i>	
INSPECTION INFORMATION					
INSPECTION DATE: 6/1/06	TIME:	INSPEC	TION NUMBER	₹:	
LEAD INSPECTOR: Steven	Cout	0			
OTHER INSPECTOR(S): Same					
INSPECTOR ACKNOWLEDGMENT		今年,因为李 和			
I performed an SPCC inspection at the facil	lity specified above.				
INSPECTOR SIGNATURE:	ven Co	uto		DATE	:: 6/6/06

EAGUEV PERSONS EN AVESTA AND AND AND AND AND AND AND AND AND AN	
FACILITY RESPONSE PLAN (FRP) APPLICABILITY	
A non-transportation related onshore facility is required to prepare and implement	an FRP as outlined in 40 CFR 112.20 if:
☐ The facility transfers oil over water to or from vessels and has a total oil storaç OR	ge capacity greater than or equal to 42,000 gallons,
The facility has a total oil storage capacity of at least 1 million gallons, and at least ☐ The facility does not have secondary containment sufficiently large to contain sufficient freeboard for precipitation. ☐ The facility is located at a distance such that a discharge could cause injury to The facility is located such that a discharge would shut down a public drinking ☐ The facility has had a reportable discharge greater than or equal to 10,000 ga	the capacity of the largest aboveground tank plus fish and wildlife and sensitive environments. water intake.
Facility has FRP: ☐ Yes ☐ No ☐ Not Required FRP Number:	
Facility has a completed and signed copy of Appendix C, Attachment C-II, "Certific Criteria."	cation of the Applicability of the Substantial Harm ☐ Yes ☐ No
Comments:	
SPCC GENERAL APPLICABILITY—40 CFR 112.1	
IS THE FACILITY REGULATED UNDER 40 CFR part 112? The completely buried oil storage capacity is over 42,000 gallons, OR the aggregations	ite aboveground oil storage capacity is over 1,320
The facility is a non-transportation-related facility engaged in drilling, producing, gadistributing, using, or consuming oil and oil products, which due to its location coulupon the navigable waters of the United States (as defined in 40 CFR 110.1).	
AFFECTED WATERWAY(S): Salusbury Plan Ris	er DISTANCE: abuts river
PATH:	
Note: The following storage capacity is not considered in determining applicability of SPCC of Completely buried tanks subject to all the technical requirements of 40 CFR part 280 or Equipment subject to the authority of the U.S. Department of Transportation, U.S. Department of Memoranda of Understanding dated November 24, 1971, and November 4 Any facility or part thereof used exclusively for wastewater treatment (production, recovit treatment). Containers smaller than 55 gallons. Permanently closed containers.	a state program approved under 40 CFR part 281. rtment of the Interior, or Minerals Management Service, 8, 1993.
Does the facility have an SPCC Plan?	☐ Yes ☑/No
Comments: Facilité le unde construction	and adding 14,000 sal
Comments: Facility is under construction AST for generators. Draft SPCC ha	s been prepared by COM
REQUIREMENTS FOR PREPARATION AND IMPLEMENTATION OF A	SPCC PLAN—40 CFR 112.3
Date facility began operations:	
Date of initial SPCC Plan preparation: Current pla	an version (date/number):
112.3(a) For facilities in operation prior to August 16, 2002: • Plan amended by February 17, 2006	□Yes □No □NA
Amended Plan implemented by August 18, 2006	□ Yes □ No □ NA
For facilities beginning operation between August 17, 2002, and Augu 2006, Plan prepared and fully implemented by August 18, 2006	ıst 18, □ Yes □ No □ NA

REQUIR	EMENTS FOR PREPARAT	ION AND IMPLEMENT	TATION OF A SE	PCC PLAN	N—40 CFR 1	12.3		
112.3(b) & (c)	For facilities beginning opera implemented before beginning		6, Plan prepared a	and fully		□ Yes	□No	□NA
• Pt • Pt • Pl ap • Pr	Professional Engineer certificate is familiar with the requirement or agent has visited and examan is prepared in accordance wellicable industry standards and occedures for required inspectionan is adequate for the facility	nts of 40 CFR part 112 nined the facility ith good engineering prac I the requirements of 40 C	tice including cons FR part 112		f	☐ Yes☐ Yes☐ Yes☐ Yes☐ Yes☐ Yes☐ Yes☐ Yes	□ No	
PE Name	:	License No.:	State:		Date of certific	cation:		
112.3(e)	Plan available onsite if facility (If located at nearest field offi					□ Yes	□No	□NA
Comment	s:							
AMEND	MENT OF SPCC PLAN BY	REGIONAL ADMINIST	RATOR (RA)—4	0 CFR 11	2.4			
112.4(a)	Has the facility discharged a re than 1,000 gallons of oil in a si discharges in any 12-month pe	ingle discharge or more th	an 42 gallons in ea		more	□ Yes	□No	
	If yes, was information sull	bmitted to the RA as requi	ired in §112.4(a)?			□ Yes	□No	□NA
	Date(s) of reportable disciWere they reported to the					□Yes	□No	□NA
112.4(d), ((e) Have changes required by t	he RA been implemented	in the Plan and/or	facility?		□ Yes	□No	□NA
Comments	S:			4				
AMENDA	MENT OF SPCC PLAN BY T	THE OWNER OR OPER	RATOR—40 CFF	R 112.5	4.4			
112.5(a)	Has there been a change at t	he facility that materially a	affects the potentia	l for a discl	narge?	□Yes	□No	□NA
	If so, was the Plan amend	ed within six months of the	e change?			□ Yes	□No	□NA
112.5(b)	Review and evaluation of the	Plan documented at least	t once every 5 yea	rs?		□Yes	□No	□NA
	Following Plan review, and months to include more ef		The state of the s		n six	□ Yes	□No	□NA
	Professional Engineer certification §112.3(d)	tion of any technical Plan	amendments in ac	ccordance v	vith	□ Yes	□No	□NA
Name:		License No.:	State:		Date of certific	ation:		
Reason for	amendment:						1	
Amendmer	nts implemented within six mon	ths of any Plan amendme	nt			□ Yes	□No	□NA
Comments	•		14				111	

GENERA	L SPCC REQUIREMENTS—40 CFR 112.7	PLAN	FIELD
Manageme	ent approval at a level of authority to commit the necessary resources to fully implement the Plan	Yes □ No	0
Name:	Title:	Date:	
Plan follow	s sequence of the rule or provides a cross-reference of requirements in the Plan and the rule	□ Yes	
	for facilities, procedures, methods, or equipment not yet fully operational, details of their installation of are discussed (Note: Relevant for inspection evaluation and testing baselines.)	☐ Yes ☐ No ☐ NA	
112.7(a)(2)	If there are deviations from the requirements of the rule, the Plan states reasons for nonconformance	☐ Yes ☐ No ☐ NA	
	Alternative measures described in detail and provide equivalent environmental protection (Note: Inspector should document if the environmental equivalence is implemented in the field)	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
DOSCHIDE GA	ach deviation and reasons for nonconformance:		
112.7(a)(3)	Plan includes diagram with location and contents of all regulated containers (including completely buried tanks otherwise exempt from the SPCC requirements), transfer stations, and connecting pipes	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
112.7(a)(3)	Plan addresses each of the following:		Tage 1
(i)	For each container, type of oil and storage capacity (see Appendix A)	☐ Yes☐ No☐ NA	☐ Yes ☐ No ☐ NA
(ii)	Discharge prevention measures, including procedures for routine handling of products	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	Discharge or drainage controls, such as secondary containment around containers, and other structures, equipment, and procedures for the control of a discharge	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	Countermeasures for discharge discovery, response, and cleanup (both facility's and contractor's resources)	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
(v)	Methods of disposal of recovered materials in accordance with applicable legal requirements	☐ Yes ☐ No ☐ NA	
	Contact list and phone numbers for the facility response coordinator, National Response Center, cleanup contractors contracted to respond to a discharge, and all Federal, State, and local agencies who must be contacted in the case of a discharge as described in §112.1(b)	☐ Yes ☐ No ☐ NA	
Comments:			

	L SPCC REQUIREMENTS—40 CFR 112.7	PLAN	FIELD
112.7(a)(4)	Plan includes information and procedures that enable a person reporting a discharge as described in §112.1(b) to relate information on the exact address or location and phone number of the facility; the date and time of the discharge; the type of material discharged; estimates of the total quantity discharged; estimates of the quantity discharged as described in §112.1(b); the source of the discharge; a description of all affected media; the cause of the discharge; any damages or injuries caused by the discharge; actions being used to stop, remove, and mitigate the effects of the discharge; whether an evacuation may be needed; and the names of individuals and/or organizations who have also been contacted (Not required if a facility has an FRP)	□ Yes □ No □ NA	
112.7(a)(5)	Plan organized so that portions describing procedures to be used when a discharge occurs will be readily usable in an emergency (Not required if a facility has an FRP)	☐ Yes ☐ No ☐ NA	
112.7(b)	Plan includes a prediction of the direction, rate of flow, and total quantity of oil that could be discharged for each type of major equipment failure where experience indicates a reasonable potential for equipment failure	☐ Yes☐ No☐ NA	☐ Yes ☐ No ☐ NA
	Appropriate containment and/or diversionary structures provided to prevent a discharge as described in §112.1(b) before cleanup occurs. The entire containment system, including walls and floors, are capable of containing oil and are constructed to prevent escape of a discharge from the containment system before cleanup occurs. (1) For onshore facilities, one of the following or its equivalent: (i) dikes, berms, or retaining walls sufficiently impervious to contain oil, (ii) curbing, (iii) culverting, gutters or other drainage systems, (iv) weirs, booms or other barriers, (v) spill diversion ponds, (vi) retention ponds, or (vii) sorbent materials (See Appendix A)	□ Yes □ No □ NA	□ Yes □ No □ NA
	Determination (c) of investigation	TV	
112.7(d)	Determination(s) of impracticability of secondary containment	☐ Yes ☐ No	
112.7(d)	If YES, is the impracticability of secondary containment clearly demonstrated?		□ Yes □ No □ NA
112.7(d)		□ No □ Yes □ No	□No
112.7(d)	If YES, is the impracticability of secondary containment clearly demonstrated?	□ No □ Yes □ No	□No
12.7(d)	If YES, is the impracticability of secondary containment clearly demonstrated? Comments concerning impracticability determination(s) for secondary containment: If impracticability determination is made, for bulk storage containers, periodic integrity testing of	□ No □ Yes □ No □ NA	□ No □ NA
12.7(d)	If YES, is the impracticability of secondary containment clearly demonstrated? Comments concerning impracticability determination(s) for secondary containment: If impracticability determination is made, for bulk storage containers, periodic integrity testing of containers and leak testing of the valves and piping associated with the container is conducted If impracticability determination is made, unless facility has FRP:	□ No □ Yes □ No □ NA □ Yes □ No □ NA	□ No □ NA
12.7(d)	If YES, is the impracticability of secondary containment clearly demonstrated? Comments concerning impracticability determination(s) for secondary containment: If impracticability determination is made, for bulk storage containers, periodic integrity testing of containers and leak testing of the valves and piping associated with the container is conducted If impracticability determination is made, unless facility has FRP: (1) Contingency Plan following 40 CFR part 109 (see Appendix C checklist) is provided AND (2) Written commitment of manpower, equipment, and materials required to control and remove	□ No □ Yes □ No □ NA	□ No □ NA □ Yes □ No □ NA

NERAL SPCC REQUIREMENTS—40 CFR 112.7	PLAN	FIELD
.7(f) Personnel, training, and oil discharge prevention procedures		
Training of oil-handling personnel in operation and maintenance of equipment to prevent discharges; discharge procedure protocols; applicable pollution control laws, rules and regulations; general facility operations; and contents of SPCC Plan	□ Yes □ No □ NA	□ Yes □ No □ NA
Person designated as accountable for discharge prevention at the facility	□ Yes □ No □ NA	☐ Yes ☐ No ☐ NA
Discharge prevention briefings conducted at least once a year for oil handling personnel	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
7(g) Security (excluding production facilities)		
Facility fully fenced and gates are locked and/or guarded when facility is unattended	□ Yes □ No □ NA	☐ Yes ☐ No ☐ NA
Master flow and drain valves and any other valves permitting direct outward flow of the container's contents to the surface have adequate security measures so that they remain in the closed position when in non-operating or non-standby status	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
Pump starter controls locked in "off" position and accessible only to authorized personnel when in non-operating/non-standby status	☐ Yes☐ No☐ NA	□ Yes □ No □ NA
Loading/unloading connections of oil pipelines or facility piping securely capped or blank-flanged when not in service or when in standby service for an extended period of time, including piping that is emptied of liquid content either by draining or by inert gas pressure	☐ Yes ☐ No ☐ NA	□ Yes □ No □ NA
Adequate facility lighting commensurate with the type and location of the facility that assists in the discovery of discharges occurring during hours of darkness and to prevent discharges occurring through acts of vandalism	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
7(h) Tank car and tank truck loading/unloading rack*		
Does loading/unloading area (the location adjacent to the loading or unloading rack) drainage flow to catchment basin or treatment facility? Yes No If NO, quick drainage system used	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
Containment system holds capacity of the largest single compartment of a tank car/truck loaded/unloaded at the facility	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
Physical barriers, warning signs, wheel chocks, or vehicle brake interlock system in loading/unloading areas (the location adjacent to the loading or unloading rack) to prevent vehicles from departing before complete disconnection of flexible or fixed oil transfer lines	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
Lower-most drains and all outlets on tank cars/trucks inspected prior to filling/departure, and, if necessary ensure that they are tightened, adjusted, or replaced to prevent liquid discharge while in transit	☐ Yes . ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	□No	□ No
	Training of oil-handling personnel in operation and maintenance of equipment to prevent discharges; discharge procedure protocols; applicable pollution control laws, rules and regulations; general facility operations; and contents of SPCC Plan Person designated as accountable for discharge prevention at the facility Discharge prevention briefings conducted at least once a year for oil handling personnel (7(g) Security (excluding production facilities) Facility fully fenced and gates are locked and/or guarded when facility is unattended Master flow and drain valves and any other valves permitting direct outward flow of the container's contents to the surface have adequate security measures so that they remain in the closed position when in non-operating or non-standby status Pump starter controls locked in "off" position and accessible only to authorized personnel when in non-operating/non-standby status Loading/unloading connections of oil pipelines or facility piping securely capped or blank-flanged when not in service or when in standby service for an extended period of time, including piping that is emptied of liquid content either by draining or by inert gas pressure Adequate facility lighting commensurate with the type and location of the facility that assists in the discovery of discharges occurring during hours of darkness and to prevent discharges occurring through acts of vandalism (7(h) Tank car and tank truck loading/unloading rack* Does loading/unloading area (the location adjacent to the loading or unloading rack) drainage flow to catchment basin or treatment facility? □ Yes □ No • If NO, quick drainage system used Containment system holds capacity of the largest single compartment of a tank car/truck loaded/unloaded at the facility Physical barriers, warning signs, wheel chocks, or vehicle brake interlock system in loading/unloading areas (the location adjacent to the loading or unloading rack) to prevent vehicles from departing before complete disconnection of flexible or fixed oil t	Training of oil-handling personnel in operation and maintenance of equipment to prevent discharges; discharge procedure protocols; applicable pollution control laws, rules and regulations; general facility operations; and contents of SPCC Plan Person designated as accountable for discharge prevention at the facility Discharge prevention briefings conducted at least once a year for oil handling personnel Preson designated as accountable for discharge prevention at the facility Discharge prevention briefings conducted at least once a year for oil handling personnel Preson designated as accountable for discharge prevention at the facility Discharge prevention briefings conducted at least once a year for oil handling personnel Preson designated as accountable for discharge prevention at the facility is unattended Preson designated as accountable for discharge prevention at the facility is unattended Preson designated as accountable for discharge prevention at the facility is unattended Preson designated as accountable for discharge prevention at the facility is unattended Preson designated as accountable for discharge prevention at the facility is unattended Preson designated as accountable facility is unattended Preson designated as accountable for facility facility is unattended Preson designated as accountable facility piping accurety capped or the container's contents to the surface position when in non-operating on-standby status Preson designated facility is unattended Preson designated facility is unattended for the facility piping securety capped or blank-flanged when not in non-operating functions of discharges occurring the facility is unattended at the facility piping securety capped or blank-flanged when not

CEEN	STRANE/SENCES REQUIREMENTS—40 CFR 112.7	IN PLAN A	NEW PERENDE
112.7(i) Brittle fracture evaluation of field-constructed aboveground containers		
112.7(Brittle fracture evaluation is conducted after tank repair/alteration/change in service that might affect the risk of a discharge or after a discharge/failure due to brittle fracture or other catastrophe, and appropriate action taken as necessary (for field-constructed aboveground containers)	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
112.7(j) State rules, regulations and guidelines and conformance with applicable sections of 40 CFR part 112		
112.7(j) Discussion of conformance with applicable more stringent State rules, regulations, and guidelines and other effective discharge prevention and containment procedures listed in 40 CFR part 112	☐ Yes☐ No☐ NA	
Comm			
ONSH	IORE FACILITIES (EXCLUDING PRODUCTION)—112.8/112.12	PLAN	FIELD
112.8(b)/112.12(b) Facility Drainage		
ı	Drainage from diked storage areas is restrained by valves, OR manually activated pumps or ejectors are used and the condition of the accumulation is inspected prior to discharge to ensure no oil will be discharged.	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
(2)	Valves from diked storage areas are manual, open-and-closed design (not flapper-type drain valves)	☐ Yes ☐ No ☐ NA	□ Yes □ No □ NA
	If drainage is released directly to a watercourse and not into an onsite wastewater treatment plant, storm water inspected per §112.8(c)(3)(ii), (iii), and (iv) or §112.12(c)(3)(ii), (iii), and (iv)	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	rainage from undiked areas with a potential for discharge designed to flow into ponds, lagoons, or atchment basins to retain oil or return it to facility. Catchment basin located away from flood areas.*	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	facility drainage not engineered as in (b)(3), facility equipped with a diversion system to retain oil in the cility in the event of a discharge*	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	re facility drainage waters continuously treated in more than one treatment unit and pump transfer is needed \square No \square If YES:	ed?	
•	Two "lift" pumps available and at least one permanently installed	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
•	Facility drainage systems engineered to prevent a discharge as described in §112.1(b) in the case of equipment failure or human error	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
Comme	e provisions apply only when a facility drainage system is used for containment		

ON	SHORE FACILITIES (EXCLUDING PRODUCTION)—112.8/112.12	PLAN	FIELD
112.	8(c)/112.12(c) Bulk Storage Containers (See Appendix A of this checklist)		
(1)	Containers compatible with material stored and conditions of storage such as pressure and temperature	□ Yes □ No □ NA	☐ Yes ☐ No ☐ NA
(2)	Secondary containment to hold capacity of largest container and sufficient freeboard for precipitation	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	Diked areas sufficiently impervious to contain discharged oil	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	Alternatively, any discharge to a drainage trench system will be safely confined in a facility catchment basin or holding pond	☐ Yes☐ No☐ NA	☐ Yes ☐ No ☐ NA
	Is there drainage of uncontaminated rainwater from diked areas into a storm drain or open watercourse? ☐ Yes ☐ No If YES:		
	(i) Bypass valve normally sealed closed	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	(ii) Retained rainwater is inspected to ensure that its presence will not cause a discharge as described in §112.1(b)	☐ Yes☐ No☐ NA	☐ Yes ☐ No ☐ NA
((iii) Bypass valve opened and resealed under responsible supervision	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
((iv) Adequate records of drainage are kept; for example, records required under permits issued in accordance with 40 CFR 122.41(j)(2) and (m)(3)	□ Yes □ No □ NA	☐ Yes ☐ No ☐ NA
	For completely buried metallic tanks installed on or after January 10, 1974 (if not exempt from SPCC regulati to all of the technical requirements of 40 CFR part 280 or 281):	on because	subject
	Corrosion protection with coatings or cathodic protection compatible with local soil conditions	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	Regular leak testing conducted	□ Yes □ No □ NA	☐ Yes ☐ No ☐ NA
	Partially buried or bunkered metallic tanks protected from corrosion with coatings or cathodic protection compatible with local soil conditions	□ Yes □ No □ NA	☐ Yes ☐ No ☐ NA
Com	ments:		

ONS	SHORE FACILITIES (EXCLUDING PRODUCTION)—112.8/112.12	PLAN	FIELD
112.	8(c)/112.12(c) Bulk Storage Containers (continued)		
(6)	Aboveground containers integrity tested by visual inspection and another technique such as hydrostatic testing, radiographic testing, ultrasonic testing, acoustic emissions testing, or another system of non-destructive shell testing on a regular schedule and whenever material repairs are made	☐ Yes ☐ No ☐ NA	□ Yes □ No □ NA
	Container supports and foundations regularly inspected	□ Yes □ No □ NA	☐ Yes ☐ No ☐ NA
	Outside of containers frequently inspected for signs of deterioration, discharges, or accumulation of oil inside diked areas	☐ Yes ☐ No ☐ NA	□ Yes □ No □ NA
	Records of inspections and tests maintained	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
(7) L	Leakage through defective internal heating coils controlled: Steam returns and exhaust lines from internal heating coils that discharge into an open water source are monitored for contamination, OR Steam returns and exhaust lines pass through a settling tank, skimmer, or other separation or retention system	□ Yes □ No □ NA	□ Yes □ No □ NA
ir c s p	Each container equipped with at least one of the following for liquid level sensing: (i) high liquid level alarms with an audible or visual signal at a constantly attended operation or surveillance station, or audible air vent in smaller facilities, (ii) high liquid level pump cutoff devices set to stop flow at a predetermined container content level, (iii) direct audible or code signal communication between container gauger and pumping station, (iv) fast response system (such as digital computers, telepulse, or direct vision gauges) and a person is present to monitor gauges and the overall filling of bulk storage containers, (v) liquid level sensing devices regularly tested to ensure proper operation	□ Yes □ No □ NA	□ Yes □ No □ NA
	Effluent treatment facilities observed frequently enough to detect possible system upsets that could cause a ischarge as described in §112.1(b)	□ Yes □ No □ NA	☐ Yes ☐ No ☐ NA
	Visible discharges which result in a loss of oil from the container, including but not limited to seams, gaskets, piping, pumps, valves, rivets, and bolts are promptly corrected and oil in diked areas is promptly removed	□ Yes □ No □ NA	☐ Yes ☐ No ☐ NA
(11)	Mobile or portable containers positioned to prevent a discharge to prevent a discharge as described in §112.1(b).	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
	Mobile or portable containers have secondary containment with sufficient capacity to contain the largest single compartment or container and sufficient freeboard for precipitation	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
Comm	nents:		

ON	SHORE FACILITIES (EXCLUDING PRODUCTION)—112.8/112.12	PLAN	FIELD		
112.8(d)/112.12(d) Facility transfer operations, pumping, and facility process					
(1)	Buried piping installed or replaced on or after August 16, 2002 has protective wrapping or coating		☐ Yes ☐ No ☐ NA		
	Buried piping installed or replaced on or after August 16, 2002 is cathodically protected or otherwise satisfies corrosion protection standards for piping in 40 CFR part 280 or 281	☐ Yes☐ No☐ NA	☐ Yes ☐ No ☐ NA		
	Exposed buried piping is inspected for deterioration and corrosion damage is examined and corrected	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA		
(2)	Piping terminal connection at the transfer point is marked as to origin and capped or blank-flanged when not in service or in standby service for an extended time	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA		
(3)	Pipe supports are properly designed to minimize abrasion and corrosion and allow for expansion and contraction	☐ Yes ☐ No ☐ NA	□ Yes □ No □ NA		
(4)	Aboveground valves, piping, and appurtenances such as flange joints, expansion joints, valve glands and bodies, catch pans, pipeline supports, locking of valves, and metal surfaces are inspected regularly	☐ Yes ☐ No ☐ NA	□ Yes □ No □ NA		
	Integrity and leak testing conducted on buried piping at time of installation, modification, construction, relocation, or replacement	☐ Yes ☐ No ☐ NA	□ Yes □ No □ NA		
(5)	Vehicles warned so that no vehicle endangers aboveground piping and other oil transfer operations	☐ Yes ☐ No ☐ NA	□Yes □No □NA		

Comments:

	ADDITIONAL COMMENTS
Rule Provision	Comment

	PHOTO DOCUMENTATION LOG						
Photo Number	Description (include date and location)						

SPCC FIELD INSPECTION AND PLAN REVIEW TABLE

Appendix A: Documentation of Field Observations for Containers and Associated Requirements

Inspectors should use this table to document observations of containers as needed.

Containers and Piping

Check containers for leaks, specifically looking for: drip marks, discoloration of tanks, puddles containing spilled or leaked material, corrosion, cracks, and localized dead vegetation, and standards/specifications of construction.

Check foundation for: cracks, discoloration, puddles containing spilled or leaked material, settling, gaps between container and foundation, and damage caused by vegetation roots.

Check piping for: droplets of stored material, discoloration, corrosion, bowing of pipe between supports, evidence of stored material seepage from valves or seals, and localized dead vegetation. (Document in comments section of §112.8(d) / §112.12(d).)

Secondary Containment (Active and Passive)

Check secondary containment for: containment system (including walls and floor) ability to contain oil such that oil will not escape the containment system before cleanup occurs, proper sizing, cracks, discoloration, presence of spilled or leaked material (standing liquid), erosion, corrosion, and valve conditions.

Check dike or berm systems for: level of precipitation in dike/available capacity, operational status of drainage valves (closed), dike or berm impermeability, debris, erosion, impermeability of the earthen floor/walls of diked area, and location/status of pipes, inlets, drainage around and beneath containers, presence of oil discharges within diked areas.

Check retention and drainage ponds for: erosion, available capacity, presence of spilled or leaked material, debris, and stressed vegetation.

Check active measures (countermeasures) for: amount indicated in plan is available and appropriate; deployment procedures are realistic; material is located so that they are readily available; efficacy of discharge detection; availability of personnel and training, appropriateness of measures to prevent a discharge as described in §112.1(b).

Container ID/ General Condition	Storage Capacity and Type of Oil	Type of Containment/ Drainage Control	Overfill Protection and Testing & Inspections
			* *
			No. 7
43 /			

SPCC INSPECTION AND TESTING CHECKLIST

Appendix B: Required Documentation of Tests and Inspections

Records of inspections and tests required by 40 CFR part 112 signed by the appropriate supervisor or inspector must be kept with the SPCC Plan for a period of three years. Records of inspections and tests conducted under usual and customary business practices will suffice. Documentation of the following inspections and tests should be kept with the SPCC Plan.

		Docume		
	Inspection or Test	Present	Not Present	Not Applicable
112.7–Ge	eneral SPCC Requirements			
	grity testing is conducted for bulk storage containers with no secondary tainment system and for which an impracticability determination has been de			
conf	grity and leak testing of valves and piping associated with bulk storage tainers with no secondary containment system and for which an aracticability determination has been made			
or o	luate field-constructed aboveground containers for potential for brittle fracture ther catastrophic failure when the container undergoes a repair, alteration, onstruction or change in service			
112.8/112	2.12—Onshore facilities (excluding production)	The French		
(b)(2)	Storm water released from facility drainage directly to a watercourse is inspected and records of drainage are kept			
(c)(3)(iv)	Rainwater released directly from diked containment areas to a storm drain or open watercourse is inspected and records of drainage are kept			
(c)(4)	Regular leak testing of completely buried metallic storage tanks			
(c)(6)	Aboveground containers, supports and foundations tested for integrity on a regular schedule	,		
(c)(6)	Outside of containers frequently inspected for deterioration, discharges or accumulations of oil inside diked areas			
(c)(8)(v)	Liquid level sensing devices regularly tested to ensure proper operation			
(c)(9) §112.1(b)	Effluent treatment facilities are observed frequently enough to detect possible system upsets that could cause a discharge as described in			
(d)(1)	When buried piping is exposed, it is carefully inspected for deterioration and corrosion damage is corrected			
(d)(4)	Aboveground valves, piping and appurtenances are regularly inspected and the general condition of flange joints, expansion joints, valve glands and bodies, catch pans, pipeline supports, locking of valves, and metal surfaces are assessed			
d)(4)	Integrity and leak testing of buried piping is conducted at time of installation, modification, construction, relocation or replacement			
Comment				

SPCC CONTINGENCY PLAN REVIEW CHECKLIST

Appendix C: 40 CFR Part 109–Criteria for State, Local and Regional Oil Removal Contingency Plans

If a facility makes an impracticability determination for secondary containment in accordance with §112.7(d), it is required to provide an oil spill contingency plan following 40 CFR part 109.

109	9.5–C	Development and implementation criteria for State, local and regional oil removal contingency plans*	Yes	No
(a)	Defi	inition of the authorities, responsibilities and duties of all persons, organizations or agencies which are to be elved in planning or directing oil removal operations.		
(b)		ablishment of notification procedures for the purpose of early detection and timely notification of an oil harge including:		
	(1)	The identification of critical water use areas to facilitate the reporting of and response to oil discharges.		
	(2)	A current list of names, telephone numbers and addresses of the responsible persons (with alternates) and organizations to be notified when an oil discharge is discovered.		
	(3)	Provisions for access to a reliable communications system for timely notification of an oil discharge, and the capability of interconnection with the communications systems established under related oil removal contingency plans, particularly State and National plans (e.g., NCP).		
gi	(4)	An established, prearranged procedure for requesting assistance during a major disaster or when the situation exceeds the response capability of the State, local or regional authority.		
(c)		risions to assure that full resource capability is known and can be committed during an oil discharge situation inding:		
	(1)	The identification and inventory of applicable equipment, materials and supplies which are available locally and regionally.		
	(2)	An estimate of the equipment, materials and supplies which would be required to remove the maximum oil discharge to be anticipated.		
	(3)	Development of agreements and arrangements in advance of an oil discharge for the acquisition of equipment, materials and supplies to be used in responding to such a discharge.		
d)		isions for well defined and specific actions to be taken after discovery and notification of an oil discharge ding:		
	(1)	Specification of an oil discharge response operating team consisting of trained, prepared and available operating personnel.		
	(2)	Predesignation of a properly qualified oil discharge response coordinator who is charged with the responsibility and delegated commensurate authority for directing and coordinating response operations and who knows how to request assistance from Federal authorities operating under existing national and regional contingency plans.		
	(3)	A preplanned location for an oil discharge response operations center and a reliable communications system for directing the coordinated overall response operations.		
	(4)	Provisions for varying degrees of response effort depending on the severity of the oil discharge.		
	(5)	Specification of the order of priority in which the various water uses are to be protected where more than one water use may be adversely affected as a result of an oil discharge and where response operations may not be adequate to protect all uses.		
		ific and well defined procedures to facilitate recovery of damages and enforcement measures as provided y State and local statutes and ordinances.		

^{*} The contingency plan should be consistent with all applicable state and local plans, Area Contingency Plans, and the National Contingency Plan (NCP).

\$EPA	United States Environme Washington, I				
		Inspection Rep	ort .		
ternamonismi entre Plance Carlo		Data System Coding (i			
Transaction Code 1	September 1997	yr/mo/day 0 6 0 6 0 1117	Inspection Type	Inspector	Fac Type 20
21		Remarks	111111	11111	1 1 1 1 166
	oring Evaluation Rating	BI QA		Reserved	to a solit control of
67 69	70 🔲	71 72	7374	75	80
Carlo and a supplement of the second of the	the same of the sa	on B: Facility Data	Jan 2010	Permit Effe	etiva Data
Name and Location of Facility Inspected (include POTW name and NPDES permit in Brockton Waster 303 Oak Hill Brockton, MA	water Treat Way	timent Plant	Entry Time/Date Exit Time/Date		iration Date
Name(s) of On-Site Representative(s)/Title		or(s)	Other Facility Data	(e.g. SIC NAICS	S. and other
David Norton			Other Facility Data descriptive informa		
Brockton Water &	& Sewer Co	utract Admi	M mult-	Sector	. Permit
508 580 7	885		In P	oTW de	
Section C: Permit Records/Reports Facility Site Review Effluent/Receiving Waters Flow Measurement		enance Pollution Properties Pollution Properties Storm Wate Combined S	nt evention	uated) MS4	
	Section D: Sun	nmary of Findings/Commodilists, including Single I	nents	es, as necessa	ny)
SEV Codes SEV Description		into es konstadajo esta.	garage sources of		
		Section 22			
	read and or review of the			to Man	
00000	asu or se				
			4 3	Editor Salah M	er en
Name(s) and Signature(s) of Inspector(s).	to	Agency/Office/Phone and EPA/SEW	Fax Numbers 617 918 17	Date 6/5	106
100					
				The same	0-505
Signature of Management Q A Reviewer		Agency/Office/Phone and	Fax Numbers	Date	

1615/28/06

INSTRUCTIONS

Section A: National Data System Coding (i.e., PCS)

Column 1: Transaction Code: Use N, C, or D for New, Change, or Delete. All inspections will be new unless there is an error in the data entered.

Columns 3-11: NPDES Permit No. Enter the facility's NPDES permit number - third character in permit number indicates permit type for U=unpermitted, G=general permit, etc.. (Use the Remarks columns to record the State permit number, if necessary.)

Columns 12-17: Inspection Date. Insert the date entry was made into the facility. Use the year/month/day format (e.g., 04/10/01 = October 01, 2004).

Column 18: Inspection Type*. Use one of the codes listed below to describe the type of inspection:

A	Performance Audit	U	IU Inspection with Pretreatment Audit	!	Pretreatment Compliance (Oversight)
B	Compliance Biomonitoring Compliance Evaluation (non-sampling)	X	Toxics Inspection Sludge - Biosolids	@	Follow-up (enforcement)
D	Diagnostic Diagnostic	#	Combined Sewer Overflow-Sampling	1	Storm Water-Construction-Sampling
F	Pretreatment (Follow-up) Pretreatment (Audit)	\$	Combined Sewer Overflow-Non-Sampling Sanitary Sewer Overflow-Sampling	}	Storm Water-Construction-Non-Sampling
I	Industrial User (IU) Inspection	8	Sanitary Sewer Overflow-Non-Sampling CAFO-Sampling	:	Storm Water-Non-Construction-Sampling
M	Complaints Multimedia	=	CAFO-Non-Sampling IU Sampling Inspection	~	Storm Water-Non-Construction- Non-Sampling
N	Spill Compliance Evaluation (Oversight)	3	IU Non-Sampling Inspection		Storm Water-MS4-Sampling
P	Pretreatment Compliance Inspection	4	IU Toxics Inspection	-	Storm Water-MS4-Non-Sampling
R	Reconnaissance	5	IU Sampling Inspection with Pretreatment IU Non-Sampling Inspection with Pretreatment	>	Storm Water-MS4-Audit
S	Compliance Sampling	0	10 Non-Sampling Inspection with Freueautient		

IU Toxics with Pretreatment

Column 19: Inspector Code. Use one of the codes listed below to describe the lead agency in the inspection.

A — State (Contractor)	O— Other Inspectors, Federal/EPA (Specify in Remarks columns)
A — State (Contractor) B — EPA (Contractor) E — Corps of Engineers J — Joint EPA/State Inspectors—EPA Lead L — Local Health Department (State) N — NEIC Inspectors	O— Other Inspectors, Federal/EPA (Specify in Remarks columns) P— Other Inspectors, State (Specify in Remarks columns) R— EPA Regional Inspector S— State Inspector T— Joint State/EPA Inspectors—State lead
L — Local Health Department (State) N — NEIC Inspectors	T — Joint State/EPA Inspectors—State lead

Column 20: Facility Type. Use one of the codes below to describe the facility.

- 1 Municipal. Publicly Owned Treatment Works (POTWs) with 1987 Standard Industrial Code (SIC) 4952.
- 2 Industrial. Other than municipal, agricultural, and Federal facilities.
- 3 Agricultural. Facilities classified with 1987 SIC 0111 to 0971.
- 4 Federal. Facilities identified as Federal by the EPA Regional Office.
- 5 Oil & Gas. Facilities classified with 1987 SIC 1311 to 1389.

Columns 21-66: Remarks. These columns are reserved for remarks at the discretion of the Region.

Columns 67-69: Inspection Work Days. Estimate the total work effort (to the nearest 0.1 work day), up to 99.9 days, that were used to complete the inspection and submit a QA reviewed report of findings. This estimate includes the accumulative effort of all participating inspectors; any effort for laboratory analyses, testing, and remote sensing; and the billed payroll time for travel and pre and post inspection preparation. This estimate does not require detailed documentation.

Column 70: Facility Evaluation Rating. Use information gathered during the inspection (regardless of inspection type) to evaluate the quality of the facility self-monitoring program. Grade the program using a scale of 1 to 5 with a score of 5 being used for very reliable self-monitoring programs, 3 being satisfactory, and 1 being used for very unreliable programs.

Column 71: Biomonitoring Information. Enter D for static testing. Enter F for flow through testing. Enter N for no biomonitoring.

Column 72: Quality Assurance Data Inspection. Enter Q if the inspection was conducted as followup on quality assurance sample results. Enter N otherwise.

Columns 73-80: These columns are reserved for regionally defined information.

Section B: Facility Data

This section is self-explanatory except for "Other Facility Data," which may include new information not in the permit or PCS (e.g., new outfalls, names of receiving waters, new ownership, other updates to the record, SIC/NAICS Codes, Latitude/Longitude).

Section C: Areas Evaluated During Inspection

Check only those areas evaluated by marking the appropriate box. Use Section D and additional sheets as necessary. Support the findings, as necessary, in a brief narrative report. Use the headings given on the report form (e.g., Permit, Records/Reports) when discussing the areas evaluated during the inspection.

Section D: Summary of Findings/Comments

Briefly summarize the inspection findings. This summary should abstract the pertinent inspection findings, not replace the narrative report. Reference a list of attachments, such as completed checklists taken from the NPDES Compliance Inspection Manuals and pretreatment guidance documents, including effluent data when sampling has been done. Use extra sheets as necessary.

*Footnote: In addition to the inspection types listed above under column 18, a state may continue to use the following wet weather and CAFO inspection types until the state is brought into ICIS-NPDES: K: CAFO, V: SSO, Y: CSO, W: Storm Water 9: MS4. States may also use the new wet weather, CAFO and MS4 inspections types shown in column 18 of this form. The EPA regions are required to use the new wet weather, CAFO, and MS4 inspection types for inspections with an inspection date (DTIN) on or after July 1, 2005.

ŞEPA ₩ee	United States Environment Washington, D.	C. 20460	ort	
vval	er Compliance II			
T. Marie Co. I.		Data System Coding (i	Inspection Type	Inspector Fac Type
Transaction Code NPDi		r/mo/day 60601117 Remarks	18	19 8 20 11
21	1111111111			
Inspection Work Days Facility Self-Mor	nitoring Evaluation Rating	BI QA 71	73 74	Reserved
	Section	n B: Facility Data		a the transfer of the terms
Name and Location of Facility Inspected include POTW name and NPDES permit Brockton Wast	water Treatn	rent Plant	Entry Time/Date	Permit Effective Date
Brockton, MA	Λ	haseI	Exit Time/Date	Permit Expiration Date
Name(s) of On-Site Representative(s)/TI Ray Lagasse Hart Engence Cumberland,	supt.	r(s)		(e.g., SIC NAICS, and other ion) Tuction
	: Areas Evaluated During	STATEMENT PROPERTY AND ADDRESS OF THE PARTY AN	ly those areas evalu	ated) MS4
Records/Reports Facility Site Review Effluent/Receiving Waters Flow Measurement	Self-Monitoring Progr Compliance Scheduk Laboratory Operations & Mainter Sludge Handling/Disp	Pollution Prospersion Storm Water	revention	
(Attach additional sheet SEV Codes SEV Description	Section D: Sumrets of narrative and check	mary of Findings/Comi dists, including Single	ments Event Violation code	es, as necessary)
Name(s) and Signature(s) of Inspector(s	ito A	gency/Office/Phone and	Fax Numbers 617 918 176	Date 5 6/5/06
Signature of Management Q A Reviewer	A	gency/Office/Phone and	Fax Numbers	Date

INSTRUCTIONS

Section A: National Data System Coding (i.e., PCS)

Column 1: Transaction Code: Use N, C, or D for New, Change, or Delete. All inspections will be new unless there is an error in the data entered.

Columns 3-11: NPDES Permit No. Enter the facility's NPDES permit number - third character in permit number indicates permit type for U=unpermitted, G=general permit, etc.. (Use the Remarks columns to record the State permit number, if necessary.)

Columns 12-17: Inspection Date. Insert the date entry was made into the facility. Use the year/month/day format (e.g., 04/10/01 = October 01, 2004).

Column 18: Inspection Type*. Use one of the codes listed below to describe the type of inspection:

A	Performance Audit	U	IU Inspection with Pretreatment Audit	1	Pretreatment Compliance (Oversight)
В	Compliance Biomonitoring	X	Toxics Inspection	0	Follow-up (enforcement)
C	Compliance Evaluation (non-sampling)	Z	Sludge - Biosolids	@	Pollow-up (enforcement)
D	Diagnostic	#	Combined Sewer Overflow-Sampling	1	Storm Water-Construction-Sampling
F	Pretreatment (Follow-up)	\$	Combined Sewer Overflow-Non-Sampling		01 W-1 011 N 01
G	Pretreatment (Audit)	+	Sanitary Sewer Overflow-Sampling	1	Storm Water-Construction-Non-Sampling
I	Industrial User (IU) Inspection		Sanitary Sewer Overflow-Non-Sampling		Storm Water-Non-Construction-Sampling
J	Complaints	1	CAFO-Sampling		
M	Multimedia	=	CAFO-Non-Sampling	~	Storm Water-Non-Construction- Non-Sampling
N	Spill	2	IU Sampling Inspection		Storm Water-MS4-Sampling
0	Compliance Evaluation (Oversight)	3	IU Non-Sampling Inspection		
P	Pretreatment Compliance Inspection	4	IU Toxics Inspection	-	Storm Water-MS4-Non-Sampling
R	Reconnaissance	5	IU Sampling Inspection with Pretreatment	,	Storm Water-MS4-Audit
S	Compliance Sampling	6	IU Non-Sampling Inspection with Pretreatment		

Column 19: Inspector Code. Use one of the codes listed below to describe the lead agency in the inspection.

A — State (Contractor) B — EPA (Contractor) E — Corps of Engineers J — Joint EPA/State Inspectors—EPA Lead L — Local Health Department (State) N — NEIC Inspectors	O— Other Inspectors, Federal/EPA (Specify in Remarks columns) P— Other Inspectors, State (Specify in Remarks columns) R— EPA Regional Inspector S— State Inspector T— Joint State/EPA Inspectors—State lead
L — Local Health Department (State) N — NEIC Inspectors	T — Joint State/EPA Inspectors—State lead

IU Toxics with Pretreatment

Column 20: Facility Type. Use one of the codes below to describe the facility.

- 1 Municipal. Publicly Owned Treatment Works (POTWs) with 1987 Standard Industrial Code (SIC) 4952.
- 2 Industrial. Other than municipal, agricultural, and Federal facilities.
- 3 Agricultural. Facilities classified with 1987 SIC 0111 to 0971.
- 4 Federal. Facilities identified as Federal by the EPA Regional Office.
- 5 Oil & Gas. Facilities classified with 1987 SIC 1311 to 1389.

Columns 21-66: Remarks. These columns are reserved for remarks at the discretion of the Region.

Columns 67-69: Inspection Work Days. Estimate the total work effort (to the nearest 0.1 work day), up to 99.9 days, that were used to complete the inspection and submit a QA reviewed report of findings. This estimate includes the accumulative effort of all participating inspectors; any effort for laboratory analyses, testing, and remote sensing; and the billed payroll time for travel and pre and post inspection preparation. This estimate does not require detailed documentation.

Column 70: Facility Evaluation Rating. Use information gathered during the inspection (regardless of inspection type) to evaluate the quality of the facility self-monitoring program. Grade the program using a scale of 1 to 5 with a score of 5 being used for very reliable self-monitoring programs, 3 being satisfactory, and 1 being used for very unreliable programs.

Column 71: Biomonitoring Information. Enter D for static testing. Enter F for flow through testing. Enter N for no biomonitoring.

Column 72: Quality Assurance Data Inspection. Enter Q if the inspection was conducted as followup on quality assurance sample results. Enter N otherwise.

Columns 73-80: These columns are reserved for regionally defined information.

Section B: Facility Data

This section is self-explanatory except for "Other Facility Data," which may include new information not in the permit or PCS (e.g., new outfalls, names of receiving waters, new ownership, other updates to the record, SIC/NAICS Codes, Latitude/Longitude).

Section C: Areas Evaluated During Inspection

Check only those areas evaluated by marking the appropriate box. Use Section D and additional sheets as necessary. Support the findings, as necessary, in a brief narrative report. Use the headings given on the report form (e.g., Permit, Records/Reports) when discussing the areas evaluated during the inspection.

Section D: Summary of Findings/Comments

Briefly summarize the inspection findings. This summary should abstract the pertinent inspection findings, not replace the narrative report. Reference a list of attachments, such as completed checklists taken from the NPDES Compliance Inspection Manuals and pretreatment guidance documents, including effluent data when sampling has been done. Use extra sheets as necessary.

*Footnote: In addition to the inspection types listed above under column 18, a state may continue to use the following wet weather and CAFO inspection types until the state is brought into ICIS-NPDES: K: CAFO, V: SSO, Y: CSO, W: Storm Water 9: MS4. States may also use the new wet weather, CAFO and MS4 inspections types shown in column 18 of this form. The EPA regions are required to use the new wet weather, CAFO, and MS4 inspection types for inspections with an inspection date (DTIN) on or after July 1, 2005.

\$EPA	United States Environmental F Washington, D.C.			
	er Compliance Ins		ort	
Watt				
Transaction Code NPDE	Section A: National Dates		Inspection Type	Inspector Fac Type
1 N 2 5 3 MARIO	CIISIQ11 12/016		18	19 [8] 20 []
21	шшш			1 1 1 1 60
Inspection Work Days Facility Self-Monit 67 69		BI QA 72 🔲	73 74	Reserved
	Section B	3: Facility Data		
Name and Location of Facility Inspected (include POTW name and NPDES permit in	The second section of the second section is a second section of the second section of the second section is a second section of the s	the same of the sa	Entry Time/Date	Permit Effective Date
Brock tow Wasting	tex Tree trees	+=:1:4		3/15/06
Brockton Wastewas 303 Oak Hell Wa	as I for the	Planett	Exit Time/Date	Permit Expiration Date
303 Oak Hell Wa Brockton, MA	02301	nage II	Exit Time/Date	Ferrin Expiration Date
Name(s) of On-Site Representative(s)/Title	e(s)/Phone and Fax Number(s)		Other Facility Data	(e.g., SIC NAICS, and other tion)
Robert Blume Walsh Constru	, supt.	of edition is a solution		
2 Commercial	iction Co.		Phase	一工
Sharon, MA			Const	ruction
Name, Address of Responsible Official/Tit			-	
Robert Blume		Contacted	Soller of the	
The stee with the	1793-9988	Yes No	The state of the	
Tel: (181)	1795-7986	AU SHIPE		
		et i trovie		
	Areas Evaluated During Ins	THE RESERVE THE PERSON NAMED IN	those areas evaluation	
Permit	Self-Monitoring Program			MS4
Records/Reports	Compliance Schedules	Pollution Pre		
	Facility Site Review Laboratory Storm Water			
Facility Site Review				
Facility Site Review Effluent/Receiving Waters	Operations & Maintenan	The state of the s	ewer Overflow	
Facility Site Review	Operations & Maintenan Sludge Handling/Dispose	al Sanitary Sev	wer Overflow	
Facility Site Review Effluent/Receiving Waters Flow Measurement	Operations & Maintenan Sludge Handling/Dispose Section D: Summar	al Sanitary Ser	wer Overflow nents	es, as necessary)
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional shee	Operations & Maintenan Sludge Handling/Dispose	al Sanitary Ser	wer Overflow nents	es, as necessary)
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional shee	Operations & Maintenan Sludge Handling/Dispose Section D: Summar	al Sanitary Ser	wer Overflow nents	es, as necessary)
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional shee	Operations & Maintenan Sludge Handling/Dispose Section D: Summar	al Sanitary Ser	wer Overflow nents	es, as necessary)
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional shee	Operations & Maintenan Sludge Handling/Dispose Section D: Summar	al Sanitary Ser	wer Overflow nents	es, as necessary)
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional shee	Operations & Maintenan Sludge Handling/Dispose Section D: Summar	al Sanitary Ser	wer Overflow nents	es, as necessary)
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional shee	Operations & Maintenan Sludge Handling/Dispose Section D: Summar	al Sanitary Ser	wer Overflow nents	es, as necessary)
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional shee	Operations & Maintenan Sludge Handling/Dispose Section D: Summar	al Sanitary Ser	wer Overflow nents	es, as necessary)
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional sheeted Sev Codes Sev Description	Operations & Maintenan Sludge Handling/Dispose Section D: Summarts of narrative and checklist	al Sanitary Set ry of Findings/Comm s, including Single E	wer Overflow nents Event Violation code	Total
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional shee	Operations & Maintenan Sludge Handling/Dispose Section D: Summarts of narrative and checklist	al Sanitary Ser	wer Overflow nents Event Violation code	Date
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional sheeted Sev Codes Sev Description	Operations & Maintenan Sludge Handling/Dispose Section D: Summarts of narrative and checklist	al Sanitary Set ry of Findings/Comm s, including Single E	wer Overflow nents Event Violation code	Date
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional sheeted Sev Codes Sev Description	Operations & Maintenan Sludge Handling/Dispose Section D: Summarts of narrative and checklist	al Sanitary Set ry of Findings/Comm s, including Single E	wer Overflow nents Event Violation code	Date
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional sheeted Sev Codes Sev Description	Operations & Maintenan Sludge Handling/Dispose Section D: Summarts of narrative and checklist	al Sanitary Set ry of Findings/Comm s, including Single E	wer Overflow nents Event Violation code	Date
Facility Site Review Effluent/Receiving Waters Flow Measurement (Attach additional sheeted Sev Codes Sev Description	Operations & Maintenan Sludge Handling/Dispose Section D: Summarts of narrative and checklist	al Sanitary Set ry of Findings/Comm s, including Single E	ents vent Violation code ax Numbers	Date

INSTRUCTIONS

Section A: National Data System Coding (i.e., PCS)

Column 1: Transaction Code: Use N, C, or D for New, Change, or Delete. All inspections will be new unless there is an error in the data entered.

Columns 3-11: NPDES Permit No. Enter the facility's NPDES permit number - third character in permit number indicates permit type for U=unpermitted, G=general permit, etc.. (Use the Remarks columns to record the State permit number, if necessary.)

Columns 12-17: Inspection Date. Insert the date entry was made into the facility. Use the year/month/day format (e.g., 04/10/01 = October 01, 2004).

Column 18: Inspection Type*. Use one of the codes listed below to describe the type of inspection:

Co	lumn 18: Inspection Type". Use one of the	coa
A	Performance Audit	
B	Compliance Biomonitoring	
C	Compliance Evaluation (non-sampling)	
D	Diagnostic	
F	Pretreatment (Follow-up)	
G	Pretreatment (Audit)	
I	Industrial User (IU) Inspection	1
J	Complaints	
M	Multimedia	
N	Spill	
0	Compliance Evaluation (Oversight)	
P	Pretreatment Compliance Inspection	
R	Reconnaissance	

Compliance Sampling

IU Inspection with Pretreatment Audit Pretreatment Compliance (Oversight) **Toxics Inspection** Follow-up (enforcement) Sludge - Biosolids Combined Sewer Overflow-Sampling Storm Water-Construction-Sampling Combined Sewer Overflow-Non-Sampling Storm Water-Construction-Non-Sampling Sanitary Sewer Overflow-Sampling Sanitary Sewer Overflow-Non-Sampling Storm Water-Non-Construction-Sampling CAFO-Sampling Storm Water-Non-Construction-Non-Sampling
 Storm Water-MS4-Sampling CAFO-Non-Sampling **IU Sampling Inspection IU Non-Sampling Inspection** Storm Water-MS4-Non-Sampling Storm Water-MS4-Audit **IU Toxics Inspection** IU Sampling Inspection with Pretreatment 5 IU Non-Sampling Inspection with Pretreatment

Column 19: Inspector Code. Use one of the codes listed below to describe the lead agency in the inspection.

A — State (Contractor) B — EPA (Contractor) E — Corps of Engineers J — Joint EPA/State Inspectors—EPA Lead L — Local Health Department (State) N — NEIC Inspectors	 O— Other Inspectors, Federal/EPA (Specify in Remarks columns) P— Other Inspectors, State (Specify in Remarks columns) R — EPA Regional Inspector S — State Inspector T — Joint State/EPA Inspectors—State lead
--	--

IU Toxics with Pretreatment

Column 20: Facility Type. Use one of the codes below to describe the facility.

- 1 Municipal. Publicly Owned Treatment Works (POTWs) with 1987 Standard Industrial Code (SIC) 4952.
- 2 Industrial. Other than municipal, agricultural, and Federal facilities.
- 3 Agricultural. Facilities classified with 1987 SIC 0111 to 0971.
- 4 Federal. Facilities identified as Federal by the EPA Regional Office.
- 5 Oil & Gas. Facilities classified with 1987 SIC 1311 to 1389.

Columns 21-66: Remarks. These columns are reserved for remarks at the discretion of the Region.

Columns 67-69: Inspection Work Days. Estimate the total work effort (to the nearest 0.1 work day), up to 99.9 days, that were used to complete the inspection and submit a QA reviewed report of findings. This estimate includes the accumulative effort of all participating inspectors; any effort for laboratory analyses, testing, and remote sensing; and the billed payroll time for travel and pre and post inspection preparation. This estimate does not require detailed documentation.

Column 70: Facility Evaluation Rating. Use information gathered during the inspection (regardless of inspection type) to evaluate the quality of the facility self-monitoring program. Grade the program using a scale of 1 to 5 with a score of 5 being used for very reliable self-monitoring programs, 3 being satisfactory, and 1 being used for very unreliable programs.

Column 71: Biomonitoring Information. Enter D for static testing. Enter F for flow through testing. Enter N for no biomonitoring.

Column 72: Quality Assurance Data Inspection. Enter Q if the inspection was conducted as followup on quality assurance sample results. Enter N otherwise.

Columns 73-80: These columns are reserved for regionally defined information.

Section B: Facility Data

This section is self-explanatory except for "Other Facility Data," which may include new information not in the permit or PCS (e.g., new outfalls, names of receiving waters, new ownership, other updates to the record, SIC/NAICS Codes, Latitude/Longitude).

Section C: Areas Evaluated During Inspection

Check only those areas evaluated by marking the appropriate box. Use Section D and additional sheets as necessary. Support the findings, as necessary, in a brief narrative report. Use the headings given on the report form (e.g., Permit, Records/Reports) when discussing the areas evaluated during the inspection.

Section D: Summary of Findings/Comments

Briefly summarize the inspection findings. This summary should abstract the pertinent inspection findings, not replace the narrative report. Reference a list of attachments, such as completed checklists taken from the NPDES Compliance Inspection Manuals and pretreatment guidance documents, including effluent data when sampling has been done. Use extra sheets as necessary.

*Footnote: In addition to the inspection types listed above under column 18, a state may continue to use the following wet weather and CAFO inspection types until the state is brought into ICIS-NPDES: K: CAFO, V: SSO, Y: CSO, W: Storm Water 9: MS4. States may also use the new wet weather, CAFO and MS4 inspections types shown in column 18 of this form. The EPA regions are required to use the new wet weather, CAFO, and MS4 inspection types for inspections with an inspection date (DTIN) on or after July 1, 2005.

			and the state of t	
OFDA	United States	Environmental Protection Agency		
SEPA		ashington, D.C. 20460		
VEIN	Water Comp	liance Inspection Report		
	Section A: N	ational Data System Coding (i.e., PCS)		
Transaction Code	NDPES	yy/mm/dd	Inspection Type	nspector Fac Type
		, , , , , , , , , , , , , , , , , , ,	mopeodon Type	Tispector Fac Type
1 N 2 3 M A 0	1 0 1 0 1 0	11 12 0 7 0 6 0 5 Remarks	17 18 C	9 20 1
21				66
Inspection Work Days Faci	ity Self-Monitoring Evaluation Ra	71 N QA	73 74 75	Reserved
		Section B: Facility Data		
Name and Location of Facility Inspected (Foinclude POTW name and NDPES permit nun BROCKTON AWRF: 303 OAK HILI	iber)		Entry Time/Date 8:30AM 6/05/07	Permit Effective Date . 12/1/2006
			Exit Time/Date 3:30PM 6/5/07	Permit Expiration Date 11/30/2011
Name(s) of On-Site Representative(s)/Title(s) JAMES LAUZON PROJECT MANAGE	/Phone and Fax Number(s)	EAV 500 550 0500	Other Facility Data	
ERNIE PERSECHINO ASSISTANT PROJECT M DAVE NORTON (city of brockton)		, FAX 508-559-0760	Facility is currently upgrade construction treatment is going	on. All secondary
MICHAEL THORESON . COMMISSIONI CITY HALL, 45 SCHOOL STREET, BROCKTON Sec X Permit	, MA 02301-9927 ction C: Areas Evaluated [Contacted X Yes No During Inspection (Check only those area		
X Records/Reports X Facility Site Review X Effluent/Receiving Waters X Flow Measurement	X Self-Monitoring Progr X Compliance Schedule X Laboratory Operations & Mainter X Sludge Handling/Disp	X Pollution Prevention X Storm Water Combined Sewer Overflow Sanitary Sewer Overflow	MS4	
Section D: Summ	ary of Findings/Comments	(Attach additional sheets of narrative an	d checklists as necessa	ry)
SEV Codes see inspection memo/report	SEV Description			
Name(s) and Signature(s) of Inspector(s) poseph Shepherd avid Burns teve Couto		Agency/Office/Phone and Fax Numbers MADEP - SERO 508 946 2756 MaDEP - SERO 508 946 2738 USEPA, OES - SEW / 671-918-1765	Date	6/6/2007
Signature of Management QA Reviewer		Agency/Office/Phone and Fax Numbers	Date	

MN/18/61


Washing Water Complia	onmental Protection Agency ton, D.C. 20460 nce Inspection Report National Data System Coding (i.e., PCS)		Form Approach OMB No. 2 Approval e	
Transaction Code NPDES 1 N 2 3 M A 0 1 0 1 0 1 0 1 0 11		Inspection Type	Ins	pector Fac Type T 20 1
21 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		Ш		66
Inspection Work Days Facility Self-Monitoring Evaluation Ratin	g B1 QA 71 N 72 N	73 74	75 Reser	rved
	Section B: Facility Data			
Name and Location of Facility Inspected (For industrial users discharg include POTW name and NDPES permit number) BROCKTON AWRF: 303 OAK HILL WAY BROCKTON MA 02401		9:30AM 6/01/0	6	Permit Effective Date 30-Sep-1998
BROCKTON AWAR. 303 OAK HILL WAT BROCKTON MIA 02401	NPDES#MA0101010	3:15PM 6/01/06		Permit Expiration Date 30-Sep-2003
JAMES LAUZON PROJECT MANAGER *VEOLIA 508-580-7885, FAX ERNIE PERSECHINO ASSISTANT PROJECT MANAGER DAVE NORTON (city of brockton) Name, Address of responsible Official/Title/Phone and Fax Number. Michael Thoreson. COMMISSIONER DPW #508 580-7135, FAX: 508 580-	Contacted X Yes No y 2004 Ped During Inspection (Check only those areas X Operations & Maintenance	unavailable for presses removed screening monst area	along fine. I period of tim , redundancy er in place r CSO/SSO (Pollution P Multimedia	Diversion pipe to be ne. y to centrifuge is trucking much improves screenings sewer Overflow)
		oleted phase II: ST		phase III OUT TO BID
Name(s) and Signature(s) of Inspector(s) JOSEPH SHEPHERD DAVE BURNS STEVE COUTO	Agency/Office/Phone and Fax Numbers DEP SERO LAKEVILLE 508 946-2756 DEP SERO LAKEVILLE, 508 946-2757 EPA 617 918-1765		Date	6/14/2006
Signature of Management QA Reviewer	Agency/Office/Phone and Fax Numbers		Date	

John Jalos

ADD TO THE STATE OF THE STATE O
A supplied to the second of th

Wash Water Comp	vironmental Protection Agency ington, D.C. 20460 pliance Inspection Report A: National Data System Coding (i.e., PCS)	OMB	Approved. No. 2040-0057 aval expires 10-31-95
Transaction Code	12 0 5 0 3 2 9 17	Inspection Type	Inspector Fac Type 19 S 20 1
21	Remarks	шш	
Inspection Work Days Facility Self-Monitoring Evaluation R	71 N 72 N	73 74 75	Reserved80
	Section B: Facility Data		
Name and Location of Facility Inspected (For industrial users dischinclude POTW name and NDPES permit number) BROCKTON AWRF: 303 OAK HILL WAY BROCKTON MA 02401	NPDES#MA0101010	Entry Time/Date 2:30PM 3/29/05 Exit Time/Date	Permit Effective Date 30-Sep-1998 Permit Expiration Date
		4:15PM 3/29/05	30-Sep-2003
ERNIE PERSECHINO ASSISTANT PROJECT MANAGER DAVE NORTON (city of brockton) Name, Address of responsible Official/Title/Phone and Fax Number. Michael Thoreson. COMMISSIONER DPW #508 580-7135, FAX: 508 5 CITY HALL, 45 SCHOOL STREET, BROCKTON, MA 02301-9927 Michael Thoreson is now the commissioner of public works as of Section C: Areas Evalu	Contacted X Yes No	s evaluated)	
X Permit X Flow Measurement X Records/Reports X Self-Monitoring Program X Facility Site Review X Compliance Schedules X Effluent/Receiving Waters Laboratory			SO (sewer Overflow) on Prevention edia
Section D: Summary of Findings/Com	nments (Attach additional sheets of narrative a	nd checklists as necessar	y)
WALK THROUGH FACILITY high flow management during construction construction of upgrade phase 1 IN PROGRESS FEDERAL CONSENT DECREE BEING NEGOTIATED - EPA L	ÆAD		
Name(s) and Signature(s) of Inspector(s)	Agency/Office/Phone and Fax Numbers	D	Date
DAVE BURNS	DEP SERO LAKEVILLE, 508 946-2757		
Signature of Management QA Reviewer	Agency/Office/Phone and Fax Numbers	D	ate

EPA Form 3560-3 (electronic version) (Rev 9-94) Previous editions are obsolete.



		ton, D.C. 2040	60			2040-0057
	Water Complia	nce Inspection	n Report		Approval	expires 10-31-95
	Section A:	National Data	System Coding (i.e., PCS)			
	NPDES 0 1 0 1 0 1 0 1 1	12 0 2	yy/mm/dd 0 7 1 0 17 narks	Inspection Type 18 C L		spector Fac Type 9 T 20 1 J
Inspection Work Days Facility	y Self-Monitoring Evaluation Rating		B1 QA			erved
0,000	70			73 74	4 75	80
Name and Location of Facility Inspecte	d (For industrial users dischargin		Facility Data	Entry Time/I	Data	Permit Effective Date
include POTW name and NDPES perm		g to I O I W, an	30	9:00AM 7/10/0		30-Sep-1998
BROCKTON AWRF: 303 OAK HILL WA		NPDES#MA	A0101010	Exit Time/Da 4:00:00PM 7/1	te	Permit Expiration Date 30-Sep-2003
HUGH SPRURWAY PROJECT DIRECT USFILTER Name, Address of responsible Official/I ROBERT SMITH COMMISSIONER DPV CITY HALL, 45 SCHOOL STREET, BRO	Citle/Phone and Fax Number. N #508 580-7135, FAX: 508 580-71		Contacted X Yes No			
CITTIALL, 43 SCHOOL STREET, BRO						
X Permit Records/Reports X Facility Site Review X Effluent/Receiving Waters	X Flow Measurement Self-Monitoring Program Compliance Schedules X Laboratory	Х	- operations to transferance	15 /2 30 1		(sewer Overflow) Prevention
Section	n D: Summary of Findings/Comm	ents (Attach ad	lditional sheets of narrative a	nd checklists as n	ecessary)	
INSPEDTION OF FACILITY FOR						
Name(s) and Signature(s) of Inspector(s joseph shepherd, dave burns, ERIC HALL		DEP SERO I	ice/Phone and Fax Numbers LAKEVILLE, 508 946-2756, 9 918-1880	508 945 2738	Da	te
Signature of Management QA Reviewer		Agency/Offic	ce/Phone and Fax Numbers		Dat	iced pos
EPA Form 3560-3 (electronic version) (Rev	y 9-94) Previous editions are obsolete	е.		Ir	Data Litials	por

	United States Environ Washingto Water Complian	on, D.C. 2046	0			OMB	Approved. No. 2040-0057 oval expires 10-31-95
			System Coding (i	i.e., PCS)			
Transaction Code 1 N 2 3 M A	NPDES 0 1 0 1 0 1 0 1 1		y/mm/dd		Inspection Ty	ype	Inspector Fac Type 19 T 20 1
21		Rem		111	Ш	Ш	60
Inspection Work Days Facility 67 0 2 . 0 69	Self-Monitoring Evaluation Rating 70	71	B1	QA 72. N	73	74 75	Reserved
		Section B: I			_		
Name and Location of Facility Inspected include POTW name and NDPES permit	number)	g to POTW, als	0		Entry Tin 10:00AM 1		Permit Effective Date 30-Sep-1998
BROCKTON AWRF: 303 OAK HILL WAY	7 BROCKTON MA 02401	NPDES#MA	0101010		Exit Time 4:30:00PM		Permit Expiration Date 30-Sep-2003
Name(s) of On-Site Representative(s)/Tit HUGH SPRURWAY PROJECT DIRECTO USFILTER Name, Address of responsible Official/Tit	R * 508-580-7885, FAX 508-559	-0760			Other Fac	cility Data	
ROBERT SMITH COMMISSIONER DPW CITY HALL, 45 SCHOOL STREET, BROO		59	Contacted X Yes	No No			
	Section C: Areas Evaluate	ed During Inspe	ction (Check onl	y those areas	evaluated)		
Permit Records/Reports X Facility Site Review X Effluent/Receiving Waters	Permit Flow Measurement X Operations & Maintenance CSO/SSO (sewe Records/Reports Self-Monitoring Program X Sludge Handling/Disposal Pollution Prever Facility Site Review Compliance Schedules Pretreatment Multimedia		media				
Section	D: Summary of Findings/Comme	ents (Attach ad	ditional sheets of	narrative an	d checklists a	as necessary	0
INSPEDTION OF FACILITY FOR	O&M AND HOUSEKEEPING IMP	PROVEMENTS					
Name(s) and Signature(s) of Inspector(s)		Agency/Offi	ce/Phone and Fa	x Numbers			Date
JOE SHEPHERD JEFFERY GOULD		DEP SERO LAKEVILLE, 508 946-2756 DEP SERO LAKEVILLE, 508 946-2757					
Simulation (M.							
Signature of Management QA Reviewer		Agency/Offic	e/Phone and Fax	Numbers		D	Date Deed PCIA
EPA Form 3560-3 (electronic version) (Rev	9-94) Previous editions are obsolete					Ini	tials for

	가장이 그렇게 되었다면 하면 하는 것이 이 이 집에 가지를 보았다. 이 지난 사람들은 이 사람들은 이 사람들은 이 사람들은 것이다.